

2022

Northbridge Slum & Blight Inventory



New Village Target Area

Report compiled by the Pioneer Valley
Planning Commission for the Town of
Northbridge

Table of Contents

Introduction.....	1
Background.....	1
Target Area Map.....	3
Methodology of Slum and Blight Inventory.....	4
Results of Slum and Blight Inventory.....	4
Appendix A: Northbridge Board of Selectmen Certification as an area of Slum and Blight.....	8
Appendix B: Baseline Information Form for CDBG Activities to Prevent or Eliminate Conditions of Slum or Blight.....	9
Appendix C: CDBG Property Inventory and Ratings.....	13
Appendix D: CDBG Public Infrastructure Inventory and Ratings.....	214
Appendix E: Maps.....	234

Introduction

The Town of Northbridge, Massachusetts, with the assistance of the Pioneer Valley Planning Commission (PVPC), has completed an inventory of the New Village neighborhood in order to determine if the area qualifies as “slum and blighted.” The designation will allow the Town to apply for funding critical to revitalizing the area. The town received designation in 2006 in the New Village target area. This current inventory is meant to update and expand the designation, allowing the town to continue eliminating the current conditions of blight on an area wide basis. It will also prevent further blight by addressing marginal properties that could, if left unassisted, deteriorate further. Specifically, the designation will allow Northbridge to continue with its work on infrastructure improvements, housing rehabilitation and other activities that support neighborhoods revitalization.

Inventory results show that the **New Village target area meets the definition and criteria to be considered a “Slum and Blighted” area.** The boundaries of Northbridge’s Slum and Blight target areas were determined by identifying areas with high concentrations of properties displaying signs of deferred maintenance, disinvestment, and abandonment. New Village consists of primarily rental residential properties with some owner-occupied single-family homes. More than 25 percent of the properties within New Village have experienced physical deterioration of buildings and abnormally low property values. In addition, more than 52 percent of the public infrastructure is in poor or fair condition and is in a general state of deterioration based on an infrastructure assessment conducted by PVPC.

Background

Northbridge was a prominent mill town during the early American Industrial Revolution given its abundant natural resources and proximity to Worcester and Providence. The greatest industrial growth occurred at Mumford River Falls where an early cotton manufactory was built near the iron foundry in 1809, with workers’ housing and two more cotton mills by 1830. Work began on creating a mill village in 1814 in what is today, Rockdale. The row-style houses that were constructed for the mill workers are still the predominant housing type in this neighborhood today. This development resulted in Rockdale becoming a major transportation hub for the region. Providence Road, the Central Turnpike, and the Providence and Worcester Railroad all intersected in Rockdale.

Northbridge’s industrial heritage is most notably known for the Whitin family who specialized in cotton yard goods and state-of-the-art textile machinery. Their operations took place in what became Whitinsville. By 1865, the Whitin family had created worker cottages and tenements, a residential area for management, numerous large estates, a library, a high school, and the Whitinsville National Bank. At its peak, over three-fourths of the male residents of Northbridge were employed by the Whitin family. However, in 1923 the depression caused the

closure of cotton mills throughout the region. The Whitinsville Cotton Company, the Linwood Cotton Company, and the mills in Rockdale and Riverdale were forced to close their doors. The only surviving company was the Whitin Machine Works. This was until the late 1940s when worker strikes led to its decline. By the 1950s, the Whitins' sold their businesses, housing units, and farm.

The closure of the once thriving mills has resulted in disinvestment in public infrastructure and housing. The proposed slum and blight target area includes the area of Northbridge surrounding Arcade Pond. It extends north on North Main Street to Village House of Pizza, east on Main Street to the Northbridge Fire Department, and west on Main Street to the intersection of Border Street. This area belongs to U.S Census Tract 7501. The New Village Target Area Map on page 3 shows the boundaries of this slum and blight inventory.


Within the New Village target area, there are:

- 199 structures
- 21,046 linear feet of roads
- 36,604.6 linear feet of sidewalks

New Village Target Area Map



6/9/2022, 12:45:44 PM



Sources: Esri, HERE, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

Methodology of Slum and Blight Inventory

In order to determine the level of deterioration of buildings in the target areas, PVPC staff completed field surveys of all the properties from January through April 2022. Assessing slum and blight requires viewing certain structures components including: roofing, windows and doors, exterior walls, porch/stairs/deck, foundation, storefront and signage, and parking lots. PVPC staff evaluated each structure component as excellent, good, fair, or poor, according to the MA DHCD guidelines. After assessing each individual component, staff gave each structure an overall property rating. Conditions were documented through the Field Maps application by taking photographs and notes. Staff also used property cards from the Town of Northbridge's database to assess each structure's age and the respective property's total assessed value.

Results of the Slum and Blight Inventory

This assessment was conducted in accordance with the guidelines established by the Massachusetts Department of Housing and Community Development (DHCD) and the United States Department of Housing and Urban Development (HUD). PVPC, with help from the Town of Northbridge, also assessed the public infrastructure as part of the Slum and Blight Inventory. The staff of the Community Development department at PVPC conducted the building and public infrastructure inventory from January through April 2022. In order to be considered as "Slum and Blighted," an area must meet the following criteria:

1. The area must meet the Massachusetts's definition of substandard, blighted, or decadent areas as stated in MGL Ch. 121B.
2. Additionally, the area must meet either one of the two conditions specified below:
 - a. The area must also have at least 25% of its properties experience one or more of the following conditions:
 - i. Physical deterioration of buildings or improvements;
 - ii. Abandonment of properties;
 - iii. Chronic high occupancy turnover rates or chronic high vacancy rates in commercial or industrial buildings;
 - iv. Significant declines in property values or abnormally low property values relative to other areas in the community; or
 - v. Known or suspected environmental contamination
 - OR
 - b. The public improvements throughout the area are in a general state of deterioration

Both Criteria 1 and 2 have been met in the New Village target area. Massachusetts General Law Chapter 121B defines a *slum, blighted or decadent area* as “an area which is detrimental to safety, health, morals, welfare or sound growth of a community because of the existence of buildings which are out of repair, physically deteriorated, unfit for human habitation, or obsolete, or in need of major maintenance of repair.” By viewing Table 1, it is clear that the proposed slum and blight target areas of Rockdale and New Village have met the criteria set by DHCD and HUD.

Table 1: Criteria Checklist for New Village Target Area

Criteria Number	Criteria for Slum & Blight Designation	Met Criteria?	# of Buildings	% of Buildings
1	Physical deterioration of buildings or properties	Yes	75	38%
2	Abandonment of Property	No	0	0
3	Chronic high occupancy turnover rates, OR	-	-	-
	Chronic high vacancy rates	-	-	-
4	Significant decline in property values, OR			
	Abnormally low property values			
5	Known or suspected environmental contamination	0	0	0
		Met Criteria?	# of Public Improvements	% of Public Improvements
6	Public improvements throughout the Area are in a general state of deterioration	Yes	7	88%

From the assessment, PVPC calculated that of the 189 structures within the target area, 72 of those structures are considered to be in fair or poor condition (see Table 2), according to the definitions provided by DHCD and HUD. Table 2 below provides a breakdown of the total amount of blighted structures by land use.

Table 2: Total Percentage of Blighted Structures by Property Land Use in New Village

	Residential	Commercial	Inst/Gov't	Mixed Use	Industrial	Total
Total Structures	191	6	2	0	0	199
Total Blighted	97	2	1	0	0	100
% Blighted	51%	33%	50%	0	0	50%

Table 3 below provides a summary of the public improvements in fair/poor condition. Of the eight public improvements that were assessed, seven of them fit the criteria of being in a general state of deterioration. When calculating the percentage of sidewalks in fair/poor condition, only streets with sidewalks were included. When calculating the percentage of curbing in fair/poor condition, streets without curbing were given a poor rating. The Town of Northbridge recently upgraded their streetlights; therefore, streets that had streetlights present were given a good rating and streets that did not have streetlights were given a poor rating. Lastly, in stances where water and sanitary sewer data were missing, a poor rating was given based on the outdated material of the infrastructure.

Table 3: Summary of Public Improvement Inventory in New Village

Met Criteria?	Public Improvement	Amount in Fair/Poor Condition	% in Fair/Poor Condition
Yes	Roadway	10,191.5 linear feet	68%
Yes	Parking	3 parking lots	50%
Yes	Sidewalks	32,293.6 linear feet	79%
Yes	Curbing	32,293.6 linear feet	79%
No	Streetlights		11%
Yes	Water	17,131.27 linear feet	74%
Yes	Sanitary Sewer	19,876.87 linear feet	100%
Yes	Storm Drainage	11,814.17 linear feet	58%

Supporting documentation as well as infrastructure and individual property evaluation sheets are provided in the Appendices. Figures 2, 3, 4, and 5 located below provide a sample of the properties that fall under fair or poor condition.



Condition: Fair

Figure 2: A residential structure at 6-8 Crescent St



Condition: Fair

Figure 3: A residential structure at 33-39 North Main St



Condition: Poor

Figure 4: Residential structure at 58-68 Overlook St



Condition: Poor

Figure 5: Residential structure at 18-21 Water St

Appendix A: Northbridge Board of Selectmen Certification as an area of Slum and Blight



**TOWN OF NORTHBRIDGE
OFFICE OF THE TOWN MANAGER
NORTHBRIDGE TOWN HALL
7 MAIN STREET
WHITINSVILLE, MASSACHUSETTS 01588
Phone- (508) 234-2095 Fax- (508) 234-7640
www.northbridgemass.org**

**Adam D. Gaudette
Town Manager**

June 13, 2022

Based on information provided in the Slum and Blight Inventory for Northbridge, Massachusetts dated June 2022, the Northbridge Board of Selectmen hereby certifies that the designated NEW VILLAGE TARGET AREA IS in disrepair with recognizable and patterns of disinvestment. As such, the area meets the Commonwealth's definition of substandard, blighted, or decadent areas as stated in MGL Chapter 121A and 121B.

Motion by: Seleena Canice

Second: Tom Melia

Vote: ✓ Yes No

Certified by: Charles Ampagoomian Jr.
Charles Ampagoomian Jr., Chairman
NORTHBRIDGE BOARD OF SELECTMEN

Date: 13-JUN-2022

Appendix B: Baseline Information Form for CDBG Activities to Prevent or Eliminate Conditions of Slum or Blight: Area Basis

Base-line Information Form For CDBG Activities To Prevent or Eliminate Conditions of Slums or Blight: Area Basis			
Documentation Category	Specific item	Numerical Response (# or %)	Identify on Target Area Map?
Total Acreage of Target Area: 135 acres			
Land uses as % total land area: <i>estimate the percentage of the total target area by listed item.</i>	Commercial Industrial Residential Transportation (Roads) Open Space Public/Institutional & Other	5.64% 2.09% 44.9% 14.62% 0.99% 31.76%	
Distribution of buildings: <i>indicate how many of the buildings are commercial, industrial, or public in target area.</i>	# Commercial buildings # Industrial buildings # Residential buildings # Other buildings (public/institutional & other)	6 0 191 2	
Building Condition Determination:	# Total buildings in target area # Total buildings Fair and Poor % Total buildings Fair and Poor	199 100 50%	
Rank the # of Commercial buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	2 2 2 0	Yes
Rank the # of Industrial buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	0 0 0 0	
Rank the # of Residential buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	7 87 88 9	Yes
Rank the # of Public/Institutional buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	0 1 1 0	Yes
Historic Resources	Buildings on or eligible for listing in National Register	73	Yes
Roads	Total linear feet of roads Total linear feet in deterioration	21,046 10,191.5	Yes
Sidewalks	Total linear feet of sidewalks	43,528.8	Yes

	Total linear feet of sidewalks in deterioration	32,293.6	
Parking: Public or Private	# parking areas, public or private # parking areas in deterioration	6 3	Yes
Parks, Playgrounds or vacant, open space areas	# parks, playgrounds, open spaces # parks, playgrounds, open spaces in deterioration	1	Yes
Other public improvements: <i>examples: sewer lines, lighting, landscape. List total amount; Estimate # or % in deterioration</i>	Total # Total #/% in deterioration	8 7	
Vacancy and indicators of disinvestment	# vacant commercial units # vacant industrial units # vacant residential units # vacant inst/gov/t units # vacant mixed use units	1 0 0 0 0	
Abandonment of Properties	# of abandoned buildings and lots Commercial Industrial Residential	0 0 0 0	
Chronic high occupancy turnover rates or high vacancy rates	Estimated # of commercial or industrial buildings with high occupancy turnover rates	-	
	Estimated # of commercial or industrial buildings with high vacancy rates	-	
Significant decline in property values or abnormally low property values	Estimated # of commercial or industrial buildings with significant decline in property value	-	
	Residential	-	
	Estimated # of commercial or industrial buildings with abnormally low property values	-	
	Residential	-	
Known or suspected environmental contamination	# of properties which have known or suspected environmental contamination	0	
Basic Business Data:	Estimate # of businesses operating in the target area	6	
	Estimate # of businesses that have left the target area in the last 24 months	0	
	Estimate # of businesses that have come into the target area in the last 24 months	0	

Appendix C: CDBG Property Inventory and Ratings

Street Listing of Properties Located in the Slum and Blight Study Area

MAIN STREET

HIGH STREET

CHESTNUT STREET

WATER STREET

LINDEN STREET

OAK STREET

WEST STREET

MAPLE STREET

NORTH MAIN STREET

A STREET

B STREET

C STREET

D STREET

BORDER STREET

OVERLOOK STREET

CRESCENT STREET

ARCADE STREET

LAKE STREET

LAKE TERRACE

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-7 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 377,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Excellent – asphalt shingles

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Fair – uneven stairs

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- porch/stairs show signs of wear and damage

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-15 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 321,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – moss growth
Windows and Doors	Fair – Older style, missing screens
Exterior Walls	Fair
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- walls, windows, roof show signs of wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-16 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 333,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Excellent; asphalt shingles

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- exterior upkeep well

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 17-23 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 308,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Fair – old style windows
Exterior Walls	Good
Porch/Stairs/Deck	Fair – crumbling
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair: windows/doors and porch show signs of wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 18-24 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 333,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – shingles lifting

Windows and Doors Fair – old

Exterior Walls Fair – chipped siding

Porch/Stairs/Deck Fair

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Roofing, windows/doors, walls, porch show signs of wear & age

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25-31 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 351,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – uneven, stained

Windows and Doors Fair – old style

Exterior Walls Fair – stained

Porch/Stairs/Deck Fair – uneven

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – roof, windows/doors, walls, porch/stairs show signs of age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 26-32 A St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1895
Storefront Construction:
Building Age: 127
Vacant: yes ☐ no ☒ other:
Assessed Value: 349,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – asphalt shingles

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- some signs of wear on windows/doors, otherwise good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-11 B St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 467,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair- no railings on one set
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- overall, building is in good condition despite some issues with porch/stairs/deck

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-12 B St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – roof is in good condition, but shingles over entryways need replacing

Windows and Doors Good

Exterior Walls Fair

Porch/Stairs/Deck Fair – uneven & bowed porch

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – porch and exterior walls show signs of wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13-23 B St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 468,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – exterior of the house shows signs of upkeep & overall good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 14-24 B St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 412,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Excellent – asphalt shingles

Windows and Doors Fair – Old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- house in good condition aside from age of windows/doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25-35 B St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 620,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy
Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected
Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – minor stains

Windows and Doors Fair – old

Exterior Walls Fair – stains

Porch/Stairs/Deck Fair – some uneven

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – walls, porch/stairs/dec and windows/doors show wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 26-36 B St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 440,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent – asphalt shingles
Windows and Doors	Fair – old, missing screens
Exterior Walls	Fair – stained, chipped siding
Porch/Stairs/Deck	Fair – porch is uneven
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Windows/doors, walls, porch show wear and age

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 11-13 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 229,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair- missing shingles, staining
Windows and Doors	Poor- old windows/doors, chipped paint/trim
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- physical deterioration around door frame, roof is fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 19-21 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 268,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – stained, moss growth
Windows and Doors	Fair – old
Exterior Walls	Fair – holes in siding, moss growth
Porch/Stairs/Deck	Fair – moss growth, uneven
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Moss growth & age on windows/doors, roofing, exterior walls, porch

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 27-29 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 236,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – stains

Windows and Doors Fair – old

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- windows/doors and roof show stain and age

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 28-30 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 227,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing	Good
Windows and Doors	Fair- old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- aside from old windows/doors, house is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 35-37 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 242,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old windows
Exterior Walls	Fair – moss growth
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 51-53 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 236,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Poor – old, missing trim
Exterior Walls	Fair – stained
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – walls & windows/doors show wear, stain and age

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 59-61 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 250,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – moss growth
Windows and Doors	Poor – old, broken
Exterior Walls	Fair – chipped paint
Porch/Stairs/Deck	Poor – uneven, bowed wood
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor – house shows physical deterioration and wear throughout the exterior

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 73-75 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 2019
Storefront Construction:
Building Age: 3
Vacant: yes ☐ no ☒ other:
Assessed Value: 397,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Excellent

Exterior Walls Excellent

Porch/Stairs/Deck Excellent

Foundation Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent – house is mostly brand new and is in excellent condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 81-83 Border St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1917
Storefront Construction:
Building Age: 105
Vacant: yes ☐ no ☒ other:
Assessed Value: 282,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – moss growth
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from moss growth, house is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 84 Borer St
Zoning or Land Use: R-5
Commercial/Residential: Commercial
Stories: 1
General Construction: 1952
Storefront Construction:
Building Age: 70
Vacant: yes ☐ no ☒ other:
Assessed Value: 122,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – moss growth
Windows and Doors	Good
Exterior Walls	Fair – stained
Porch/Stairs/Deck	N/a
Foundation	Unknown
Storefront & Signage	Fair – excessive signage
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – building shows signs of wear and damage

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 109-113 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 2007
Storefront Construction:
Building Age: 15
Vacant: yes ☐ no ☒ other:
Assessed Value: 222,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Excellent

Windows and Doors Excellent

Exterior Walls Excellent

Porch/Stairs/Deck Excellent

Foundation Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent- newer property, kept in excellent condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 110-114 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1987
Storefront Construction:
Building Age: 35
Vacant: yes ☐ no ☒ other:
Assessed Value: 332,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – minor stains
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – Exterior kept in excellent condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 117-127 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 886,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Poor- paint in poor condition, missing railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- porch/stairs show signs of physical deterioration

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 118-128 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 947,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Fair – slightly stained in corner
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- Overall, exterior is upkeep in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 135-145 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 784,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – moss growth, staining

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Fair – paint chipping

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – some signs of wear and moss on roof and porch

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 136-146 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 732,880
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – newer doors, older windows
Exterior Walls	Fair – good siding, chipped paint along trim
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from old windows and chipped paint on trim, building is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 150-160 Border St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 2
 General Construction: 1900
 Storefront Construction:
 Building Age: 122
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 473,500
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing	Good
Windows and Doors	Poor – old, broken
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair, some broken windows/doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 163-173 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 597,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – stained
Windows and Doors	Fair – old windows, newer doors
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from old windows and stained roof, building is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 164-174 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 605,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing

Good

Windows and Doors

Fair – chipped paint on trim, missing screens

Exterior Walls

Good

Porch/Stairs/Deck

Fair – weathered stairs

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – building is in good condition aside from chipped paint on trim and missing screens on windows

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-11 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 421,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair- stained, moss growth, broken trim

Windows and Doors Poor – old, chipped

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- signs of physical deterioration on roof & windows/doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-12 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 418,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Poor – chipped siding
Porch/Stairs/Deck	Fair – cracked stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – building has chipped siding, cracked stairs and old windows/doors, shows wear/age

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13-23 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 432,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – asphalt shingles

Windows and Doors Fair – old

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Fair

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – some age/wear on porch & windows/doors, otherwise building is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 14-24 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 373,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – stained
Windows and Doors	Poor – old, broken
Exterior Walls	Good
Porch/Stairs/Deck	Fair - stains
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – roofing and windows/doors show age/wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25-35 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1909
Storefront Construction:
Building Age: 113
Vacant: yes ☐ no ☒ other:
Assessed Value: 534,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – moss growth, staining

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from staining & moss on roof, building is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 26-36 C St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 2
 General Construction: 1900
 Storefront Construction:
 Building Age: 122
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 501,300
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – stained, lifting shingles
Windows and Doors	Fair – old doors & windows
Exterior Walls	Good
Porch/Stairs/Deck	Poor – bowed wood porch with missing pieces
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair: Age, wear and deterioration can be seen on roof, windows/doors and porch

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 38-40 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 281,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – moss growth
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Fair – chipped trim, uneven
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Roofing, windows/doors & porch show signs of age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 42-44 C St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1908
Storefront Construction:
Building Age: 114
Vacant: yes ☐ no ☒ other:
Assessed Value: 283,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Fair – chipped wood
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – porch and windows/doors show age, wear and chipping

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 3 Chestnut St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1887
Storefront Construction:
Building Age: 135
Vacant: yes ☐ no ☒ other:
Assessed Value: 422,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – House is maintained in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 7 Chestnut St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1902
Storefront Construction:
Building Age: 120
Vacant: yes ☐ no ☒ other:
Assessed Value: 407,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good, brick
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – house is upkeep in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13 Chestnut St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 369,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- house shows signs of upkeep and newer fixtures

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-3 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1912
Storefront Construction:
Building Age: 110
Vacant: yes ☐ no ☒ other:
Assessed Value: 326,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing

Excellent

Windows and Doors

Poor- old, missing screen doors

Exterior Walls

Fair- some siding is broken/lifting

Porch/Stairs/Deck

Fair - weathered

Foundation

Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- deterioration of siding/trim

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-4 Crescent St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 3
 General Construction: 1910
 Storefront Construction:
 Building Age: 112
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 294,400
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Poor – significant moss growth
Windows and Doors	Good
Exterior Walls	Fair – moss growth, discoloration
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – moss growth and discoloration throughout exterior (roof and walls)

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1911
Storefront Construction:
Building Age: 111
Vacant: yes ☐ no ☒ other:
Assessed Value: 300,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – older, some broken trim
Exterior Walls	Good
Porch/Stairs/Deck	Fair - weathered
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 6-8 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 377,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Poor – significant moss growth

Windows and Doors Fair – old windows

Exterior Walls Fair – moss growth

Porch/Stairs/Deck Poor – steps crumbling

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – moss growth throughout the house

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-12 Crescent St.
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 304,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair - some moss growth

Windows and Doors Fair - old

Exterior Walls Fair - minor moss growth

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 14-16 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 292,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – minor stains

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 18-22 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 350,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 24-34 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1986
Storefront Construction:
Building Age: 36
Vacant: yes ☐ no ☒ other:
Assessed Value: 1,342,300
Other Relevant Data:



If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Good – wood siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – excellent roofing, rest of exterior is good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 44-54 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1905
Storefront Construction:
Building Age: 117
Vacant: yes ☐ no ☒ other:
Assessed Value: 521,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – moss growth, stains

Windows and Doors Fair – old

Exterior Walls Fair – some moss growth

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair, moss and staining on roof and walls

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 45-55 Crescent St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1925
Storefront Construction:
Building Age: 97
Vacant: yes ☐ no ☒ other:
Assessed Value: 540,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – overall, exterior in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-11 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 574,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Fair – trim on porch is deteriorating
Porch/Stairs/Deck	Fair – uneven stairs, weathered
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-12 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 550,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – older style windows
Exterior Walls	Good
Porch/Stairs/Deck	Fair – missing wood, faded paint
Foundation	Fair – some dislodged bricks
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13-23 D St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 2
 General Construction: 1920
 Storefront Construction:
 Building Age: 102
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 116,300
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – moss growth, stained

Windows and Doors Fair – old

Exterior Walls Fair – moss growth

Porch/Stairs/Deck Fair – stairs are stained

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 14-24 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 573,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – older windows
Exterior Walls	Poor – worn/chipped paint
Porch/Stairs/Deck	Fair – worn paint, stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor – house has chipped paint, signs of deterioration on walls, and older windows

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25-35 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 442,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – stained

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from stained roof and older windows/doors, building is in good condition

2. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 26-36 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1920
Storefront Construction:
Building Age: 102
Vacant: yes ☐ no ☒ other:
Assessed Value: 701,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Excellent

Windows and Doors Good

Exterior Walls Excellent

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – updates and maintenance, building is in good overall condition

2. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 37-47 D St.
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 3
 General Construction: 1910
 Storefront Construction:
 Building Age: 112
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 875,100
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – stained/discoloration

Windows and Doors Good

Exterior Walls Fair – stained, chipped

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Stains/chips/discoloration on roof and exterior walls

2. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 38-48 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 880,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – areas of missing shingles

Windows and Doors Fair – worn/broken screen

Exterior Walls Good

Porch/Stairs/Deck Excellent

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – some wear on roof and windows, otherwise good condition

2. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 49-59 D St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 3
 General Construction: 1910
 Storefront Construction:
 Building Age: 112
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 538,400
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Fair – old
Exterior Walls	Fair – broken trim
Porch/Stairs/Deck	Fair – bowed wood, stained stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 50-60 D St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 460,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 7-17 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 620,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair - minor stains
Windows and Doors	Fair; older doors
Exterior Walls	Good; vinyl siding
Porch/Stairs/Deck	Good; granite stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall aside from older doors and minor stains on roofing

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-14 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 454,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Excellent; asphalt shingles

Windows and Doors Excellent; new

Exterior Walls Excellent; vinyl

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent; roofing, walls and windows/doors upkept in excellent condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 16-22 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1870
Storefront Construction:
Building Age: 152
Vacant: yes ☐ no ☒ other:
Assessed Value: 468,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good - asphalt shingles
Windows and Doors	Fair - old
Exterior Walls	Fair - vinyl siding with minor stains
Porch/Stairs/Deck	Fair – stairs weathered/stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair overall, siding stains and old windows/doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 19 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1870
Storefront Construction:
Building Age: 152
Vacant: yes ☐ no ☒ other:
Assessed Value: 209,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair - lifting on edges
Windows and Doors	Poor - old with trim deteriorating
Exterior Walls	Good
Porch/Stairs/Deck	Fair - poor awning
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – deterioration on trim, roof issues

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 24-30 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 406,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 32-38 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 474,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Poor – significant moss growth, damaged
Porch/Stairs/Deck	Fair – missing/damaged concrete steps
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – damage to walls and steps

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 40-46 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1890
Storefront Construction:
Building Age: 132
Vacant: yes ☐ no ☒ other:
Assessed Value: 358,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – moss growth
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 48-54 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1895
Storefront Construction:
Building Age: 127
Vacant: yes ☐ no ☒ other:
Assessed Value: 374,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – damaged siding, worn paint
Porch/Stairs/Deck	Fair – wood railings rotted/chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair overall, rotting wood on railings, chipped paint, damaged siding

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 60-62 High St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 261,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair, light moss growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Fair

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good overall aside from moss growth on roof & age on porch/stairs

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-11 Lake St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 2
 General Construction: 1909
 Storefront Construction:
 Building Age: 113
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 524,700
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Fair – uneven, chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair- some physical deterioration seen in porch, old windows

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-12 Lake St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1870
Storefront Construction:
Building Age: 152
Vacant: yes ☐ no ☒ other:
Assessed Value: 474,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing	Good
Windows and Doors	Fair - old
Exterior Walls	Fair
Porch/Stairs/Deck	Good
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – despite good porch and roofing, windows/doors and walls show signs of age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 44 Lake St
Zoning or Land Use: R-5
Commercial/Residential: Commercial
Stories: 1
General Construction: 1922
Storefront Construction:
Building Age: 100
Vacant: yes ☐ no ☒ other:
Assessed Value: 603,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – minor stains
Foundation	Fair – minor cracking
Storefront & Signage	Good
Parking Lots	Fair
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 50 Lake St
Zoning or Land Use: R-5
Commercial/Residential:
Public/Institutional
Stories: 1
General Construction: 1959
Storefront Construction:
Building Age: 63
Vacant: yes ☐ no ☒ other:
Assessed Value: 1,248,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Unknown

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage Good

Parking Lots Good

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 56-66 Lake St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1890
Storefront Construction:
Building Age: 132
Vacant: yes ☐ no ☒ other:
Assessed Value: 532,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1 Linden St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 187,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Poor- Old style windows
Exterior Walls	Poor- rotted wood, chipped paint
Porch/Stairs/Deck	Poor- rotted wood, chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor- windows and doors, walls and porch show signs of physical deterioration

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 Linden St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 337,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good; asphalt shingles

Windows and Doors Good

Exterior Walls Good; vinyl siding

Porch/Stairs/Deck Good; granite stairs

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – overall, house is maintained in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-12 Linden St.
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1882
Storefront Construction:
Building Age: 140
Vacant: yes ☐ no ☒ other:
Assessed Value: 241,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Fair

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- Roofing, windows and doors, walls, foundations upkept in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13 Linden St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 3
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 302,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good; asphalt shingles

Windows and Doors Fair; old

Exterior Walls Fair; dirty

Porch/Stairs/Deck Good

Foundation Good; brick

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good, windows/doors & walls show signs of wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 14 Linden St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2.25
General Construction: 1921
Storefront Construction:
Building Age: 101
Vacant: yes ☐ no ☒ other:
Assessed Value: 394,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – weathered, stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from some age/wear on stairs, house is in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 15 Linden St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2.25
General Construction: 1897
Storefront Construction:
Building Age: 125
Vacant: yes ☐ no ☒ other:
Assessed Value: 318,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair - some moss growth on edges

Windows and Doors Good

Exterior Walls Good - wood siding

Porch/Stairs/Deck Good - granite stairs

Foundation Good - brick

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – aside from some moss on roof, house is in good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 16 Linden St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1921
Storefront Construction:
Building Age: 101
Vacant: yes ☐ no ☒ other:
Assessed Value: 408,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Excellent

Windows and Doors Excellent

Exterior Walls Excellent

Porch/Stairs/Deck Excellent

Foundation Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 168-178 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2.25
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 554,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – some plant growth in gutters

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 186-196 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1870
Storefront Construction:
Building Age: 152
Vacant: yes ☐ no ☒ other:
Assessed Value: 538,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – few shingles are lifting

Windows and Doors Fair – old

Exterior Walls Fair – some stains

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – windows/doors & walls show signs of age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 193 Main St
 Zoning or Land Use: R-5
 Commercial/Residential: Government
 Stories: 3
 General Construction: 1922
 Storefront Construction:
 Building Age: 100
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 1,897,500
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Unknown
Windows and Doors	Poor – some broken
Exterior Walls	Fair – some cracks
Porch/Stairs/Deck	n/a
Foundation	Unknown
Storefront & Signage	Good
Parking Lots	Fair – few cracks
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – windows/doors and walls show signs of deterioration

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 202 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1850
Storefront Construction:
Building Age: 172
Vacant: yes ☐ no ☒ other:
Assessed Value: 243,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair - older
Exterior Walls	Poor – faded paint
Porch/Stairs/Deck	Fair – wood floor in poor condition
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 205 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 245,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – stains, moss growth
Porch/Stairs/Deck	Good – granite stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – overall good despite stains/moss growth on walls and age of windows/doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 208 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1840
Storefront Construction:
Building Age: 182
Vacant: yes ☐ no ☒ other:
Assessed Value: 307,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – stairs are uneven
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – house in overall good condition aside from uneven stairs

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 211-213 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 260,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 216 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1814
Storefront Construction:
Building Age: 208
Vacant: yes ☐ no ☒ other:
Assessed Value: 254,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair - stains
Windows and Doors	Good
Exterior Walls	Fair – dirt/moss growth
Porch/Stairs/Deck	Poor – porch flooring in poor condition
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – overall good aside from porch flooring and dirt/moss growth on walls

2. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 223-225 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 235,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Fair – old
Exterior Walls	Fair – chipping, dirt
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – fair overall due to age of windows/doors, walls/porch showing age/wear/chipped paint

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 224-234 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 2
General Construction: 1870
Storefront Construction:
Building Age: 152
Vacant: yes ☐ no ☒ other:
Assessed Value: 469,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old doors
Exterior Walls	Poor – missing siding, faded paint
Porch/Stairs/Deck	Fair
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – walls show signs of physical deterioration, older doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 240-242 Main St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1890
Storefront Construction:
Building Age: 132
Vacant: yes ☐ no ☒ other:
Assessed Value: 244,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old windows
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall aside from older windows

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 243-245 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 243,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Fair – worn
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – walls, windows & doors show signs of age, deterioration

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 252-254 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1905
Storefront Construction:
Building Age: 117
Vacant: yes ☐ no ☒ other:
Assessed Value: 284,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 253-255 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 311,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 258-260 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1907
Storefront Construction:
Building Age: 115
Vacant: yes ☐ no ☒ other:
Assessed Value: 293,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 272 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1890
Storefront Construction:
Building Age: 132
Vacant: yes ☐ no ☒ other:
Assessed Value: 259,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Poor – significant paint chip/fading
Porch/Stairs/Deck	Fair – bushes covering entrance
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Bushes cover entrance, paint on walls is chipped and fading

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 414-420 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 337,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Fair – olderstyle
Exterior Walls	Good
Porch/Stairs/Deck	Fair – weathered
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 424-430 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 330,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – some shingles lifting slightly

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Fair – stains, weathered

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 434-440 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 363,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – worn stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 444-446 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 261,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair
Exterior Walls	Good
Porch/Stairs/Deck	Fair – worn
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 452 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.5
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 198,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – asphalt shingles

Windows and Doors Fair – old

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Poor – uneven, chipped

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 458-464 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 353,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – asphalt shingles

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Fair – some chipped

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 476-478 Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 330,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Fair – older
Exterior Walls	Fair – minor stains
Porch/Stairs/Deck	Good
Foundation	Fair – stains

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-3 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 286,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair - few shingles lifting

Windows and Doors Good

Exterior Walls Good- wood siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good, some signs of wear on roof, otherwise good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1882
Storefront Construction:
Building Age: 140
Vacant: yes ☐ no ☒ other:
Assessed Value: 264,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Fair - faded
Porch/Stairs/Deck	Excellent
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good – overall house is maintained in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-12 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 273,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 11 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1888
Storefront Construction:
Building Age: 134
Vacant: yes ☐ no ☒ other:
Assessed Value: 389,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair - minor chips
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13-15 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 257,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – shingles lifting
Windows and Doors	Fair – old, broken screens
Exterior Walls	Fair – old, stained, some siding is broken
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 14-16 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 278,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 17-19 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 256,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – old
Exterior Walls	Fair – few broken pieces of siding
Porch/Stairs/Deck	Fair – some stains, uneven steps
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 18-20 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 346,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 21-23 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 315,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Excellent – freshly painted
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall aside from old windows/doors

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 22-24 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 286,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – staining
Windows and Doors	Fair – older windows
Exterior Walls	Fair – dirt/moss growth present
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25-27 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 364,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old, chipped paint on trim
Exterior Walls	Fair – siding is lifting in some areas
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 26-28 Maple St
Zoning or Land Use: R-3
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1882
Storefront Construction:
Building Age: 140
Vacant: yes ☐ no ☒ other:
Assessed Value: 327,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 4 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Commercial
Stories: 1
General Construction: 2018
Storefront Construction:
Building Age: 4
Vacant: yes ☐ no ☒ other:
Assessed Value: 1,134,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Excellent
Foundation	Excellent
Storefront & Signage	Excellent
Parking Lots	Excellent
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 22-24 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 245,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – lifting shingles, stained

Windows and Doors Poor – old, broken

Exterior Walls Fair

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 23-29 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 305,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – minor stains

Windows and Doors Good

Exterior Walls Fair – moss growth

Porch/Stairs/Deck Fair – no railings

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 32-34 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 262,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – some shingles lifting

Windows and Doors Poor – old

Exterior Walls Fair – stained

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – windows/doors, walls and roof show signs of age, wear and damage

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 33-39 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1850
Storefront Construction:
Building Age: 172
Vacant: yes ☐ no ☒ other:
Assessed Value: 349,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – staining
Windows and Doors	Fair – old/broken window
Exterior Walls	Poor – missing/damaged siding
Porch/Stairs/Deck	Fair – broken concrete, no railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – much of exterior shows signs of age, wear and disrepair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 40-42 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 245,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair - small awning in poor condition

Windows and Doors Fair – older

Exterior Walls Fair – minor holes in siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 50 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.5
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 209700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – stained, some lifting shingles

Windows and Doors Good

Exterior Walls Poor – lifting siding

Porch/Stairs/Deck Fair – no railing

Foundation Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 56-58 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 245,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – no shingles/roofing material on porch roof

Windows and Doors Fair – old

Exterior Walls Fair – stained, trim is unattached on porch

Porch/Stairs/Deck Fair – stained, no railings

Foundation Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 61-67 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 379,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Excellent

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 66-68 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 255,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – stains, lifting shingles

Windows and Doors Fair – older

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 85-95 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 544,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – staining
Windows and Doors	Fair – older windows
Exterior Walls	Fair – misaligned siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 86-88 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 322,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – old siding, discolored
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 96-98 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1900
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 280,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Fair – old

Exterior Walls Fair

Porch/Stairs/Deck Good

Foundation Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair overall, walls and windows/doors show age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 108-112 North Main St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 3
 General Construction: 1910
 Storefront Construction:
 Building Age: 112
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 343,600
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair- older
Exterior Walls	Good- some staining
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good- windows and doors in fair condition, but house is overall upkept in good condition

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 115-117 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 204,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Poor- moss growth
Windows and Doors	Fair- old windows
Exterior Walls	Poor- significant mold/moss growth
Porch/Stairs/Deck	Fair – no railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor- roofing and walls show signs of physical deterioration

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 138-142 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 298,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – lifting shingles
Windows and Doors	Poor – older, some broken
Exterior Walls	Good
Porch/Stairs/Deck	Fair – railings are only on one side
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 148-150 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1919
Storefront Construction:
Building Age: 103
Vacant: yes ☐ no ☒ other:
Assessed Value: 398,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good – some stains
Windows and Doors	Fair – older
Exterior Walls	Poor – faded, chipping
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 151-161 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 475,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – mold/moss growth, missing trim
Porch/Stairs/Deck	Fair – Old/rusted railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 160-162 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1917
Storefront Construction:
Building Age: 105
Vacant: yes ☐ no ☒ other:
Assessed Value: 330000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – right half of roof looks new

Windows and Doors Fair – old

Exterior Walls Fair - some stains

Porch/Stairs/Deck Fair – no railings

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – windows and doors, walls show signs of age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 170-172 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 321,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Excellent

Windows and Doors Fair

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 173-183 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 943,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good condition overall

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 182-184 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1919
Storefront Construction:
Building Age: 103
Vacant: yes ☐ no ☒ other:
Assessed Value: 326,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – few stains

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 199 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Commercial
Stories: 1
General Construction: 1920
Storefront Construction:
Building Age: 102
Vacant: yes ☐ no ☒ other:
Assessed Value: 341,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	Good
Parking Lots	Good
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 205 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Commercial
Stories: 1
General Construction: 1920
Storefront Construction:
Building Age: 102
Vacant: yes ☐ no ☒ other:
Assessed Value: 42,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Excellent
Foundation	Excellent
Storefront & Signage	Poor – no signage
Parking Lots	Good
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 206 North Main St
Zoning or Land Use: R-5
Commercial/Residential: Commercial
Stories: 1
General Construction: 1956
Storefront Construction:
Building Age: 66
Vacant: yes ☐ no ☒ other:
Assessed Value: 349,100
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	n/a
Foundation	Unknown
Storefront & Signage	Fair – excessive signage
Parking Lots	Fair – faded paint, some cracks
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-3 Oak St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 277,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair; moss growth
Windows and Doors	Good
Exterior Walls	Good; vinyl siding
Porch/Stairs/Deck	Good; granite stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-4 Oak St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1800
Storefront Construction:
Building Age: 222
Vacant: yes ☐ no ☒ other:
Assessed Value: 239,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – older style
Exterior Walls	Fair – rotted wood trim, damaged siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	Physical deterioration: awning is rotting

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – some physical deterioration, rotted wood trim on walls, damaged siding, older windows

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 Oak St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 262,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair - moss growth
Windows and Doors	Fair - old
Exterior Walls	Fair - chipped siding
Porch/Stairs/Deck	Good - granite stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Roofing, windows/doors and walls show signs of age, wear and damage

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 6-8 Oak St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 241,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-11 Oak St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 206,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good - asphalt shingles
Windows and Doors	Fair - old
Exterior Walls	Fair - stains
Porch/Stairs/Deck	Poor – rusted, weathered
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – windows/doors, walls, porch/stairs show age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13-14 Oak St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1881
Storefront Construction:
Building Age: 141
Vacant: yes ☐ no ☒ other:
Assessed Value: 327,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair - shingles lifting
Windows and Doors	Good
Exterior Walls	Good - vinyl siding
Porch/Stairs/Deck	Fair - granite stairs with worn wooden deck
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair; porch/stairs and roof show signs of wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-3 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1940
Storefront Construction:
Building Age: 82
Vacant: yes ☐ no ☒ other:
Assessed Value: 270,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Poor – missing glass
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Fair – broken steps
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor – house shows signs of physical deterioration on windows, porch and exterior walls

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-8 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 1,217,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	Good
--------------	------

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good: overall good condition of exterior

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1917
Storefront Construction:
Building Age: 105
Vacant: yes ☐ no ☒ other:
Assessed Value: 348,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – lifted shingles
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – wood flooring in poor shape
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair: overall good aside from wood flooring on porch in poor shape and lifted shingles on roof

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-19 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 518,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – older windows
Exterior Walls	Poor – significant mold/moss growth, faded paint
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-20 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 3
General Construction: 1923
Storefront Construction:
Building Age: 99
Vacant: yes ☐ no ☒ other:
Assessed Value: 533,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Excellent

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 21-31 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 499,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 22-32 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1914
Storefront Construction:
Building Age: 108
Vacant: yes ☐ no ☒ other:
Assessed Value: 548,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – minor stains
Porch/Stairs/Deck	Fair – some chipped paint
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 33-43 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 512,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – minor stains

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 34-44 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 727,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – some broken, door missing
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 46-56 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 552,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Poor – old, uneven, stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – Windows/doors, porch/stairs show age and wear

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 58-68 Overlook St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1915
Storefront Construction:
Building Age: 107
Vacant: yes ☐ no ☒ other:
Assessed Value: 552,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing

Good

Windows and Doors

Poor – some broken

Exterior Walls

Poor – some holes, stains

Porch/Stairs/Deck

Fair - uneven

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 12-16 Water St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 318,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair- older style windows
Exterior Walls	Poor- damaged wood, chipped paint
Porch/Stairs/Deck	Poor- damaged wood
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 18-20 Water St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 210,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good – asphalt shingles
Windows and Doors	Poor – broken window
Exterior Walls	Poor – chipped with broken trim
Porch/Stairs/Deck	Fair – uneven
Foundation	Poor – hole
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 22-28 Water St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 318,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good; asphalt shingles

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 30-32 Water St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 228,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair; stains with minor moss growth

Windows and Doors Good

Exterior Walls Good; vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 48-54 Water St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 345,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 78-84 Water St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 318,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Poor – older style windows, broken
Exterior Walls	Poor – missing/rotted wood
Porch/Stairs/Deck	Fair – missing railings, stained, some deteriorating
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-3 West St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1901
Storefront Construction:
Building Age: 121
Vacant: yes ☐ no ☒ other:
Assessed Value: 238,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good - asphalt shingles
Windows and Doors	Good
Exterior Walls	Good - vinyl siding
Porch/Stairs/Deck	Fair - minor moss growth
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-4 West St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 245,200
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Good – solar panels

Windows and Doors Good

Exterior Walls Excellent

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 West St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 2
 General Construction: 1880
 Storefront Construction:
 Building Age: 142
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 356,800
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair - minor stains
Windows and Doors	Good
Exterior Walls	Fair - stained
Porch/Stairs/Deck	Fair - uneven stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-11 West St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 239,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Poor - stained with moss growth
Windows and Doors	Poor - very old with chipped siding
Exterior Walls	Poor - stained with moss growth
Porch/Stairs/Deck	Fair - moss growth
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 149-158A Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories:
General Construction:
Storefront Construction:
Building Age:
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Excellent

Windows and Doors Excellent

Exterior Walls Excellent

Porch/Stairs/Deck Excellent

Foundation Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-8 A St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 73,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 43-45 Border St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 177,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – stained
Windows and Doors	Fair – damaged door
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 39-41 C St
 Zoning or Land Use: R-5
 Commercial/Residential: Residential
 Stories: 2
 General Construction: 2003
 Storefront Construction:
 Building Age: 19
 Vacant: yes ☐ no ☒ other:
 Assessed Value: 180,900
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – stained
Windows and Doors	Good
Exterior Walls	Fair – significant moss growth
Porch/Stairs/Deck	Good
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-4 Maple St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1892
Storefront Construction:
Building Age: 130
Vacant: yes ☐ no ☒ other:
Assessed Value: 173,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good – granite stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 231-233 Main St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 142,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 6-8 West St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 175,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Fair – minor paint chipping
Foundation	Excellent
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 36-38 Water St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1880
Storefront Construction:
Building Age: 142
Vacant: yes ☐ no ☒ other:
Assessed Value: 171,700
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 37-51 High St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2
General Construction: 1988
Storefront Construction:
Building Age: 34
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – weathered wood
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 6 High St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1
General Construction: 1975
Storefront Construction:
Building Age: 47
Vacant: yes ☐ no ☒ other:
Assessed Value: 310,000
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-11 Linden St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1897
Storefront Construction:
Building Age: 125
Vacant: yes ☐ no ☒ other:
Assessed Value: 537,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 6-8 Maple St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2
General Construction: 1889
Storefront Construction:
Building Age: 133
Vacant: yes ☐ no ☒ other:
Assessed Value: 377,300
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – faded siding near roof
Porch/Stairs/Deck	Fair – minor chips
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 10-12 Oak St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1.75
General Construction: 1920
Storefront Construction:
Building Age: 102
Vacant: yes ☐ no ☒ other:
Assessed Value: 456,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Fair – minor chips
Porch/Stairs/Deck	Fair – chipped stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 37A & 37B C St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2
General Construction: 2004
Storefront Construction:
Building Age: 18
Vacant: yes ☐ no ☒ other:
Assessed Value: 294,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – minor moss growth, stains

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 76-78 North Main St
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 332,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – some shingles lifting

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-4 Lake Terrace
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1
General Construction:
Storefront Construction:
Building Age:
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data: Northbridge
Housing Authority

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – rusted railings
Foundation	Good
Storefront & Signage	
Parking Lots	Good
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-8 Lake Terrace
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1
General Construction:
Storefront Construction:
Building Age:
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data: Northbridge
Housing Authority

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – rusted railings
Foundation	
Storefront & Signage	
Parking Lots	Good

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-24 Lake Terrace
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 2
General Construction:
Storefront Construction:
Building Age:
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data: Northbridge
Housing Authority

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – older
Exterior Walls	Poor – bricks falling apart on right side of building
Porch/Stairs/Deck	Fair – steps worn
Foundation	Good
Storefront & Signage	
Parking Lots	Good
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25-28 Lake Terrace
 Zoning or Land Use:
 Commercial/Residential: Residential
 Stories: 1
 General Construction:
 Storefront Construction:
 Building Age:
 Vacant: yes ☐ no ☒ other:
 Assessed Value:
 Other Relevant Data: Northbridge
 Housing Authority

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – paint worn
Foundation	Good
Storefront & Signage	
Parking Lots	Good
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 29-32 Lake Terrace
Zoning or Land Use:
Commercial/Residential: Residential
Stories: 1
General Construction:
Storefront Construction:
Building Age:
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data: Northbridge
Housing Authority

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Poor – significant staining

Windows and Doors Fair – older

Exterior Walls Good

Porch/Stairs/Deck Fair -worn

Foundation Good

Storefront & Signage

Parking Lots Good

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 21 Crescent St
Zoning or Land Use: R-5
Commercial/Residential:
Gov't/Institutional
Stories:
General Construction: 2022
Storefront Construction:
Building Age: >1 year
Vacant: yes ☐ no ☒ other:
Assessed Value:
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	n/a
Windows and Doors	n/a
Exterior Walls	n/a
Porch/Stairs/Deck	n/a
Foundation	n/a
Storefront & Signage	n/a
Parking Lots	n/a
Other:	Vail Memorial Field

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair – under construction

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 1-3 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 298,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Poor – moss growth, shingles missing/discoloration

Windows and Doors Good

Exterior Walls Fair – areas of faded paint

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 2-4 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 257,400
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing Fair – some shingles lifting

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 5-7 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 292,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 9-11 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.5
General Construction: 1900
Storefront Construction:
Building Age: 122
Vacant: yes ☐ no ☒ other:
Assessed Value: 216,900
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – stains
Windows and Doors	Fair – older, some chipping around trim
Exterior Walls	Good – wood shingles
Porch/Stairs/Deck	Fair – some staining
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 13-15 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2.75
General Construction: 1910
Storefront Construction:
Building Age: 112
Vacant: yes ☐ no ☒ other:
Assessed Value: 296,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component

Condition

Roofing	Fair – lower portion of roof has moss growth and stains
Windows and Doors	Fair – older windows
Exterior Walls	Fair – minor stains
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 17 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 2014
Storefront Construction:
Building Age: 8
Vacant: yes ☐ no ☒ other:
Assessed Value: 247,800
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Excellent
Foundation	Excellent
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 21-23 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 1984
Storefront Construction:
Building Age: 38
Vacant: yes ☐ no ☒ other:
Assessed Value: 293,600
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

Component Condition

Roofing Excellent

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Property Data

Address: 25 Arcade St
Zoning or Land Use: R-5
Commercial/Residential: Residential
Stories: 2
General Construction: 2006
Storefront Construction:
Building Age: 16
Vacant: yes ☐ no ☒ other:
Assessed Value: 231,500
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
☐ Abandoned Property
☐ Chronic High Occupancy Turnover
☐ Chronic High Vacancy Rate
☐ Significant Decline in Property Value
☐ Abnormally Low Property Value
☐ Known or Suspected Environmental Contamination
☐ Other (please explain)
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – few stains
Porch/Stairs/Deck	Fair – porch is slanted, lattice is warped
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

Appendix D: CDBG Public Infrastructure Inventory and Ratings

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Border Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1910 & 2016

Sewer line: unknown

Road surface: 2010

Lighting: 2018

Sidewalk & curbs: 2010

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair – alligator cracks in some areas
Water Lines	Fair – 8” unlined cast iron, 10” unlined cast iron, 8” cement lined ductile iron
Sewer Lines	Poor – 8” clay
Existing Sidewalk	Good
Curbing	Good – granite
Drainage	Fair
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Good
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: North Main Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1918 & 1960

Sewer line: 1908

Road surface: 2010

Lighting: 2018

Sidewalk & curbs: 2010

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Good
Water Lines	Poor – 12" unlined cast iron, 8" cast iron
Sewer Lines	Poor – 8" clay
Existing Sidewalk	Good
Curbing	Good – granite
Drainage	Fair – minor pooling of water
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: A Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 2016

Sewer line: unknown

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: 1950

Other Relevant Data:

Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair
Water Lines	Good – 8" cement lined ductile iron
Sewer Lines	Poor – 6" clay
Existing Sidewalk	Poor – some areas with major cracks
Curbing	Fair
Drainage	Fair – some pooling of water, but not major
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: B Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 2016

Sewer line: unknown

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: 1950

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair – cracking throughout the street
Water Lines	Good – 8" cement lined ductile iron
Sewer Lines	Poor – 6" clay
Existing Sidewalk	Fair – portions have major cracks and are crumbling
Curbing	Poor – nonexistent in most places
Drainage	Good
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: C Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 2016

Sewer line: unknown

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: 1950

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface

Fair – minor cracks

Water Lines

Good – 8" cement lined ductile iron

Sewer Lines

Poor – 6" clay

Existing Sidewalk

Poor – major cracks and some crumbling; does not extend the entire length of street

Curbing

Poor – nonexistent

Drainage

Poor – pooling of water and cracks near the curbs

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: D Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1930 & 2016

Sewer line: unknown

Road surface: 2007

Lighting: 2018

Sidewalk & curbs: 1950

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface Fair – some cracks with debris piling up on edges

Water Lines Fair – 8" unlined clay

Sewer Lines Poor – 6" clay

Existing Sidewalk Fair – a few large cracks

Curbing Fair

Drainage Fair – debris piling up near curb

Parking Lot:

Lighting: Good

Trees/Landscaping: Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Overlook Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1915 & 1948

Sewer line: unknown

Road surface: 1999

Lighting: 2018

Sidewalk & curbs: 1951

Other Relevant Data:

Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface

Fair – minor cracks

Water Lines

Fair – 10" unlined cast iron, 10" cement lined (cast iron or ductile iron)

Sewer Lines

Poor – 6" and 8" clay

Existing Sidewalk

Fair – some cracks

Curbing

Poor – not very distinguished

Drainage

Good

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Poor – only one tree that's growing in the road/sidewalk

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Arcade Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1905


Sewer line: 1910

Road surface: 2021

Lighting: 2018

Sidewalk & curbs: 1951

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Good – newly paved
Water Lines	Poor – 6" and 10" unlined cast iron
Sewer Lines	Poor – 8" clay
Existing Sidewalk	Fair – cement and concrete, minor cracks
Curbing	Fair
Drainage	Good
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Good – forested with view of Arcade Pond
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Crescent Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1909, 1950 & 1967

Sewer line: 1910

Road surface: 2010

Lighting: 2018

Sidewalk & curbs: 2010

Other Relevant Data:



Please check the appropriate box.

☐ Physical Deterioration of Public Improvement
or

☒ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface Good – newly paved

Water Lines Fair – 10" unlined cast iron, 6" & 10" cement lined (cast iron or ductile iron)

Sewer Lines Poor – 8" clay

Existing Sidewalk Excellent

Curbing Excellent – granite

Drainage Good

Parking Lot:

Lighting: Good

Trees/Landscaping: Good

Park/Playground: Excellent – Vail Field

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Lake Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1918 & 1960

Sewer line: 1910

Road surface: 2016

Lighting: 2018

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface

Good

Water Lines

Fair – 10" unlined cast iron, 10" cement lined (cast iron or ductile iron)

Sewer Lines

Fair – 10" cast iron

Existing Sidewalk

Fair – only on north side of street

Curbing

Fair

Drainage

Good

Parking Lot:

Poor – Nation Guard parking lot, dirt

Lighting:

Good

Trees/Landscaping:

Good – forested with view of Arcade Pond

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Lake Terrace

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1918

Sewer line: unknown

Road surface: unknown

Lighting: 2018

Sidewalk & curbs: unknown

Other Relevant Data:



Please check the appropriate box.

☐ Physical Deterioration of Public Improvement
or

☒ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Good
Water Lines	Fair
Sewer Lines	Poor
Existing Sidewalk	Good
Curbing	Good – granite curbing
Drainage	Good
Parking Lot:	Good – Northbridge Housing Authority
Lighting:	Good
Trees/Landscaping:	Good
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Good

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Main Street

(please use a separate form for each street)

Zoning or Land Use: R-5 & R-3

Infrastructure age

Water line: 1901

Sewer line: 1908

Road surface: 2015

Lighting: 2018

Sidewalk & curbs: 1957

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface

Good

Water Lines

Fair – 10" unlined cast iron

Sewer Lines

Poor – 8" iron and 6" clay

Existing Sidewalk

Fair

Curbing

Fair

Drainage

Fair – some debris piled up

Parking Lot:

Fair

Lighting:

Good

Trees/Landscaping:

Good

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Water Street

(please use a separate form for each street)

Zoning or Land Use: I-5 & R-5

Infrastructure age

Water line: 1897 & 1907

Sewer line: 1908

Road surface: 1955

Lighting:

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Poor – dirt, gravel, large potholes
Water Lines	Fair – 6" & 8" unlined cast iron
Sewer Lines	Fair – 10" iron
Existing Sidewalk	Poor – nonexistent for a majority of the street
Curbing	Poor – nonexistent for a majority of the street
Drainage	Poor – major flooding
Parking Lot:	
Lighting:	Poor – no streetlights
Trees/Landscaping:	Poor
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: West Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1937

Sewer line: 1908

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface

Poor – uneven with cracks

Water Lines

Poor – 4" cement lined (cast iron or ductile iron)

Sewer Lines

Poor – 6" clay

Existing Sidewalk

Poor – inconsistent, cracking

Curbing

Poor – minimal curbing

Drainage

Fair – minor flooding

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Poor – no street trees or landscaping

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Oak Street

(please use a separate form for each street)

Zoning or Land Use: R-5

Infrastructure age

Water line: 1973

Sewer line: 1908

Road surface: 2003

Lighting:

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface

Fair – few cracks

Water Lines

Poor – 4" cement lined (cast iron or ductile iron)

Sewer Lines

Poor – 8" clay

Existing Sidewalk

Poor – a lot of cracking/crumbling

Curbing

Poor – minimal curbing

Drainage

Fair

Parking Lot:

Lighting:

Poor – no streetlights

Trees/Landscaping:

Poor – no street trees

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Maple Street

(please use a separate form for each street)

Zoning or Land Use: R-3

Infrastructure age

Water line: 2001

Sewer line: 1908

Road surface: 2003

Lighting: 2018

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair – few potholes
Water Lines	Good
Sewer Lines	Poor – 6" clay
Existing Sidewalk	Poor – asphalt, blends in with road
Curbing	Poor – nonexistent
Drainage	Fair
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Poor – no street trees
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Poor

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Linden Street

(please use a separate form for each street)

Zoning or Land Use: R-3

Infrastructure age

Water line: 2019

Sewer line: 1908

Road surface: 1969

Lighting: 2018

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair – some cracks
Water Lines	Good – 8” cement lined ductile iron
Sewer Lines	Poor – 6” clay
Existing Sidewalk	Poor – asphalt with cracks, blends in with street
Curbing	Poor – nonexistent
Drainage	Good
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair – some trees
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: Chestnut Street

(please use a separate form for each street)

Zoning or Land Use: R-3

Infrastructure age

Water line: 1909


Sewer line: n/a

Road surface: 2002

Lighting: 2018

Sidewalk & curbs: 1955

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Poor – alligator cracking, even, potholes
Water Lines	Fair – 10" unlined cast iron
Sewer Lines	n/a
Existing Sidewalk	Fair – asphalt, some cracks
Curbing	Poor – nonexistent in most places
Drainage	Fair
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Good – some trees
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair

1. NAME OF SLUM & BLIGHT AREA: NEW VILLAGE

Public Improvement Data

Street Name: High Street

(please use a separate form for each street)

Zoning or Land Use: R-3

Infrastructure age

Water line: 1921

Sewer line: 1910

Road surface: unknown

Lighting: 2018

Sidewalk & curbs: 1957

Other Relevant Data:



Please check the appropriate box.

☒ Physical Deterioration of Public Improvement
or

☐ The public improvement is not contributing to
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

Component

Condition

Road Surface	Poor – major cracks with divots
Water Lines	Fair – 12" unlined cast iron
Sewer Lines	Poor – 6" clay
Existing Sidewalk	Fair – wide concrete, cracks
Curbing	Fair – crumbling in some areas
Drainage	Poor – minor flooding with debris build up
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Poor – no trees
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair

Appendix E: Maps

New Village Infrastructure Rating Map



6/13/2022, 4:17:16 PM


New Village Infrastructure Overall Rating

Good

Fair

Poor

Northbridge SBIA New Village



Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri

PVPC

Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri | Massachusetts Department of Transportation (MassDOT), MassGIS |

New Village Property Rating Map



7/1/2022, 12:03:42 PM

Northbridge_Parcel_Rating

Excellent

Good

Fair

Poor

Other

Northbridge SBIA New Village

1:9,028

0 0.05 0.1 0.2 mi

0 0.07 0.15 0.3 km

Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri

PVPC

Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri | Massachusetts Department of Transportation (MassDOT), MassGIS |