

2022

# Northbridge Slum & Blight Inventory



## Rockdale Target Area

Report compiled by the Pioneer Valley  
Planning Commission for the Town of  
Northbridge

## Table of Contents

Introduction.....	1
Background.....	1
Target Area Map.....	3
Methodology of Slum and Blight Inventory.....	4
Results of Slum and Blight Inventory.....	4
Appendix A: Northbridge Board of Selectmen Certification as an area of Slum and Blight.....	8
Appendix B: Baseline Information Form for CDBG Activities to Prevent or Eliminate Conditions of Slum or Blight.....	10
Appendix C: CDBG Property Inventory and Ratings.....	14
Appendix D: CDBG Public Infrastructure Inventory and Ratings.....	341
Appendix E: Maps.....	367



## Introduction

The Town of Northbridge, Massachusetts, with the assistance of the Pioneer Valley Planning Commission (PVPC), has completed an inventory of the Rockdale neighborhood in order to determine if the area qualifies as “slum and blighted.” The designation will allow the Town to apply for funding critical to revitalizing the area. Earning this designation will allow the town to continue eliminating the current conditions of blight on an area wide basis. It will also prevent further blight by addressing marginal properties that could, if left unassisted, deteriorate further. Specifically, the designation will allow Northbridge to continue with its work on infrastructure improvements, housing rehabilitation and other activities that support neighborhoods revitalization.

Inventory results show that the **Rockdale target area meets the definition and criteria to be considered a “Slum and Blighted” area**. The boundaries of Northbridge’s Slum and Blight target areas were determined by identifying areas with high concentrations of properties displaying signs of deferred maintenance, disinvestment, and abandonment. Rockdale is primarily residential with some commercial and mixed-use properties along Route 122. More than 25 percent of buildings in Rockdale have experienced physical deterioration of buildings and abnormally low property values. Additionally, more than 51 percent of the public infrastructure is in poor or fair condition and is in a general state of deterioration based on an infrastructure assessment conducted by PVPC (Table 1).

## Background

Northbridge was a prominent mill town during the early American Industrial Revolution given its abundant natural resources and proximity to Worcester and Providence. The greatest industrial growth occurred at Mumford River Falls where an early cotton manufactory was built near the iron foundry in 1809, with workers’ housing and two more cotton mills by 1830. Work began on creating a mill village in 1814 in what is today, Rockdale. The row-style houses that were constructed for the mill workers are still the predominant housing type in this neighborhood today. This development resulted in Rockdale becoming a major transportation hub for the region. Providence Road, the Central Turnpike, and the Providence and Worcester Railroad all intersected in Rockdale.

Northbridge’s industrial heritage is most notably known for the Whitin family who specialized in cotton yard goods and state-of-the-art textile machinery. Their operations took place in what became Whitinsville. By 1865, the Whitin family had created worker cottages and tenements, a residential area for management, numerous large estates, a library, a high school, and the Whitinsville National Bank. At its peak, over three-fourths of the male residents of Northbridge were employed by the Whitin family. However, in 1923 the depression caused the closure of cotton mills throughout the region. The Whitinsville Cotton Company, the Linwood


Cotton Company, and the mills in Rockdale and Riverdale were forced to close their doors. The only surviving company was the Whitin Machine Works. This was until the late 1940s when worker strikes led to its decline. By the 1950s, the Whitins' sold their businesses, housing units, and farm.

The closure of the once thriving mills has resulted in disinvestment in public infrastructure and housing. The proposed slum and blight target area includes the Route 122 corridor and extends southwest to Wallen Way and east to School Street, concluding north at Upton Street. This area primarily belongs in the U.S Census Tract 7503, with a small southern portion in U.S Census Tract 7502.

Within the Rockdale target area, there are:


- 325 structures
- 31,559 linear feet of roads
- 25,955.3 linear feet of sidewalks

# Rockdale Target Area Map



6/9/2022, 12:48:37 PM

1:18,056



Sources: Esri, HERE, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

## Methodology of Slum and Blight Inventory

In order to determine the level of deterioration of buildings in the target areas, PVPC staff completed field surveys of all the properties from January through April 2022. Assessing slum and blight requires viewing certain structures components including: roofing, windows and doors, exterior walls, porch/stairs/deck, foundation, storefront and signage, and parking lots. PVPC staff evaluated each structure component as excellent, good, fair, or poor, according to the MA DHCD guidelines. After assessing each individual component, staff gave each structure an overall property rating. Conditions were documented through the Field Maps application by taking photographs and notes. Staff also used property cards from the Town of Northbridge's database to assess each structure's age and the respective property's total assessed value.

## Results of the Slum and Blight Inventory

This assessment was conducted in accordance with the guidelines established by the Massachusetts Department of Housing and Community Development (DHCD) and the United States Department of Housing and Urban Development (HUD). PVPC, with help from the Town of Northbridge, also assessed the public infrastructure as part of the Slum and Blight Inventory. The staff of the Community Development department at PVPC conducted the building and public infrastructure inventory from January through April 2022. In order to be considered as "Slum and Blighted," an area must meet the following criteria:

1. The area must meet the Massachusetts's definition of substandard, blighted, or decadent areas as stated in MGL Ch. 121B.
2. Additionally, the area must meet either one of the two conditions specified below:
  - a. The area must also have at least 25% of its properties experience one or more of the following conditions:
    - i. Physical deterioration of buildings or improvements;
    - ii. Abandonment of properties;
    - iii. Chronic high occupancy turnover rates or chronic high vacancy rates in commercial or industrial buildings;
    - iv. Significant declines in property values or abnormally low property values relative to other areas in the community; or
    - v. Known or suspected environmental contamination
  - OR
  - b. The public improvements throughout the area are in a general state of deterioration

**Both Criteria 1 and 2 have been met in the Rockdale target area.** Massachusetts General Law Chapter 121B defines a *slum, blighted or decadent area* as “an area which is detrimental to safety, health, morals, welfare or sound growth of a community because of the existence of buildings which are out of repair, physically deteriorated, unfit for human habitation, or obsolete, or in need of major maintenance of repair.” By viewing Table 1, it is clear that the proposed slum and blight target area of Rockdale has met the criteria set by DHCD and HUD.

**Table 1: Criteria Checklist for Rockdale Target Area**

Criteria Number	Criteria for Slum & Blight Designation	Met Criteria?	# of Buildings	% of Buildings
1	Physical deterioration of buildings or properties	Yes	107	33%
2	Abandonment of Property	No	4	1%
3	Chronic high occupancy turnover rates, OR	No	-	-
	Chronic high vacancy rates	No	-	-
4	Significant decline in property values, OR	-	-	-
	Abnormally low property values	-	-	-
5	Known or suspected environmental contamination	-	-	-
		<b>Met Criteria?</b>	<b># of Public Improvements</b>	<b>% of Public Improvements</b>
6	Public improvements throughout the Area are in a general state of deterioration	yes	8	88%

From the assessment, PVPC calculated that of the 324 structures within the target area, 107 of those structures are considered to be in fair or poor condition (see Table 2), according to the definitions provided by DHCD and HUD. Table 2 below provides a breakdown of the total amount of blighted structures by land use.

**Table 2: Total Percentage of Blighted Structures by Property Land use in Rockdale**

	<b>Residential</b>	<b>Commercial</b>	<b>Inst/Gov't</b>	<b>Mixed Use</b>	<b>Industrial</b>	<b>Total</b>
<b>Total Structures</b>	304	14	2	5	0	325
<b>Total Blighted</b>	92	9	1	5		107
<b>% Blighted</b>	30%	64%	50%	100%	0%	33%

Table 3 below provides a summary of the public improvements in fair/poor condition. Of the eight public improvements that were assessed, seven of them fit the criteria of being in a general state of deterioration. When calculating the percentage of sidewalks in fair/poor condition, only streets with sidewalks were included. When calculating the percentage of curbing in fair/poor condition, streets without curbing were given a poor rating. The Town of Northbridge recently upgraded their streetlights; therefore, streets that had streetlights present were given a good rating and streets that did not have streetlights were given a poor rating. Lastly, in instances where water and sanitary sewer data were missing, a poor rating was given based on the outdated material of the infrastructure.

**Table 3: Summary of Public Improvement Inventory in Rockdale**

<b>Met Criteria?</b>	<b>Public Improvement</b>	<b>Amount in Fair/Poor Condition</b>	<b>% in Fair/Poor Condition</b>
Yes	Roadway	21,279.7 linear feet	71%
Yes	Parking	12 parking lots	80%
Yes	Sidewalks	25,668 linear feet	99%
Yes	Curbing	48,397.2 linear feet	80%
No	Street Lighting		24%
Yes	Water	28,088.6 linear feet	93%
Yes	Sanitary Sewer	15,814.7 linear feet	75%
Yes	Storm Drainage	22,879.5 linear feet	76%

Supporting documentation as well as infrastructure and individual property evaluation sheets are provided in the Appendices. Figures 2, 3, 4, and 5 located below provide a sample of the properties that fall under fair or poor condition.





Condition: Fair

**Figure 2:** A mixed use structure at 22 Beanes Lane



Condition: Poor

**Figure 3:** A commercial structure at 2184 Providence Rd



Condition: Fair

**Figure 4:** A residential structure at 2184 Providence Rd



Condition: Poor

**Figure 5:** A commercial structure at 95 Church Ave

## **Appendix A: Northbridge Board of Selectmen Certification as an area of Slum and Blight**



**TOWN OF NORTHBRIDGE  
OFFICE OF THE TOWN MANAGER  
NORTHBRIDGE TOWN HALL  
7 MAIN STREET  
WHITINSVILLE, MASSACHUSETTS 01588  
Phone- (508) 234-2095 Fax- (508) 234-7640  
[www.northbridgemass.org](http://www.northbridgemass.org)**

**Adam D. Gaudette  
Town Manager**

June 13, 2022

Based on information provided in the Slum and Blight Inventory for Northbridge, Massachusetts dated June 2022, the Northbridge Board of Selectmen hereby certifies that the designated ROCKDALE TARGET AREA IS in disrepair with recognizable and patterns of disinvestment. As such, the area meets the Commonwealth's definition of substandard, blighted, or decadent areas as stated in MGL Chapter 121A and 121B.

Motion by: Selectman Melie

Second: Selectman Canne

Vote: ✓ Yes        No

Certified by: Charles Ampagoornian Jr.  
Charles Ampagoornian Jr., Chairman  
NORTHBRIDGE BOARD OF SELECTMEN

Date: 13-Jun-2022

**Appendix B: Baseline Information Form for CDBG Activities to Prevent or Eliminate Conditions of Slum or Blight: Area Basis**

<b>Base-line Information Form</b> <b>For CDBG activities</b> <b>to prevent or eliminate conditions of slums or blight:</b> <b>Area Basis</b>			
Documentation Category	Specific item	Numerical Response (# or %)	Identify on Target Area Map?
Total Acreage of Target Area: 229 acres			
<b>Land uses as % total land area:</b> <i>estimate the percentage of the total target area by listed item.</i>	Commercial Industrial Residential Transportation (Roads) Open Space Public/Institutional & Other	8.47% 1.77% 72.75% 12.68% 2.3% 2.04%	
<b>Distribution of buildings:</b> <i>indicate how many of the buildings are commercial, industrial, or public in target area.</i>	# Commercial buildings # Mixed Use # Industrial buildings # Residential buildings # Other buildings (public/institutional & other)	14 5 0 304 2	
<b>Building Condition Determination:</b>	# Total buildings in target area # Total buildings Fair and Poor % Total buildings Fair and Poor	325 107 33%	
Rank the # of <b>Commercial</b> buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	0 5 5 4	Yes
Rank the # of <b>Industrial</b> buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	0 0 0 0	
Rank the # of <b>Residential</b> buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition Unknown	20 187 82 10 5	Yes
Rank the # of <b>Public/Institutional</b> buildings by condition	# in Excellent Condition # in Good Condition # in Fair Condition # in Poor Condition	0 1 1 0	Yes
<b>Historic Resources</b>	Buildings on or eligible for listing in National Register	19	Yes
<b>Roads</b>	Total linear feet of roads Total linear feet in deterioration	30,128 21,279.7	Yes

<b>Sidewalks</b>	Total linear feet of sidewalks Total linear feet of sidewalks in deterioration	25,955.3 25,668	Yes
<b>Parking: Public or Private</b>	# parking areas, public or private # parking areas in deterioration	15 12	Yes
<b>Parks, Playgrounds or vacant, open space areas</b>	# parks, playgrounds, open spaces # parks, playgrounds, open spaces in deterioration	2 0	Yes
<b>Other public improvements:</b> <i>examples: sewer lines, lighting, landscape. List total amount; Estimate # or % in deterioration</i>	Total # Total #/% in deterioration	8 7	
<b>Vacancy and indicators of disinvestment</b>	# vacant commercial units # vacant industrial units # vacant residential units # vacant inst/gov't units # vacant mixed use units	2 0 2 0 1	
<b>Abandonment of Properties</b>	# of abandoned buildings and lots Commercial Industrial Residential Inst/Gov't Mixed Use	2  2	
<b>Chronic high occupancy turnover rates or high vacancy rates</b>	Estimated # of commercial or industrial buildings with high occupancy turnover rates	-	
	Estimated # of commercial or industrial buildings with high vacancy rates	-	
<b>Significant decline in property values or abnormally low property values</b>	Estimated # of commercial or industrial buildings with significant decline in property value		
	Residential		
	Estimated # of commercial or industrial buildings with abnormally low property values		
	Residential		
<b>Known or suspected environmental contamination</b>	# of properties which have known or suspected environmental contamination	-	



<b>Basic Business Data:</b>	Estimate # of businesses operating in the target area	19	
	Estimate # of businesses that have left the target area in the last 24 months	-	
	Estimate # of businesses that have come into the target area in the last 24 months	-	

## Appendix C: CDBG Property Inventory and Ratings

### Street Listing of Properties Located in the Slum and Blight Study Area

ARROWHEAD AVENUE  
BEANES LANE  
CENTRAL AVENUE  
CHURCH AVENUE  
COTTAGE LANE  
CROSS PLACE  
DUGGAN WAY  
ELSTON AVENUE  
EMOND AVENUE  
FIRST AVENUE  
HUDSON STREET  
LEGION WAY  
LOVELACE LANE  
MCBRIDE STREET  
NORTH TESSIER STREET  
PLANTATION STREET  
PROVIDENCE ROAD  
SCHOOL STREET  
SOUTH MAIN STREET  
SOUTH TESSIER STREET  
SPRING HILL AVENUE  
TAFT STREET  
TESSIER LANE  
UPTON STREET  
WALLEN WAY

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 12 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 282,400  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good – asphalt shingles
Windows and Doors	Fair - older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – moss growth and stains
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 15 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 187,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Excellent
-------------------	-----------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 22 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 279,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing                      Good – minor lifting of shingles

Windows and Doors      Good

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck       Fair – Moss growth

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 25 Wallen Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1989  
 Storefront Construction:  
 Building Age: 33  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 275,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### **Property Data**

Address: 35 Wallen Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1989  
 Storefront Construction:  
 Building Age: 33  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 253,300  
 Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### **Component**                      **Condition**

Roofing                              Excellent

Windows and Doors            Excellent

Exterior Walls                    Excellent

Porch/Stairs/Deck              Excellent

Foundation                        Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### **Property Data**

Address: 36 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 246,700  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### **Component**

#### **Condition**

Roofing                      Good – solar panels cover most of the roof

Windows and Doors      Good

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck        Good

Foundation                Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 45 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 315,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Excellent
-------------------	-----------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 48 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 228,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good – vinyl siding
Porch/Stairs/Deck	Excellent
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 55 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 170,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 58 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no x other:  
Assessed Value: 317,400  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Unknown

Windows and Doors

Good

Exterior Walls

Good – vinyl siding

Porch/Stairs/Deck

Excellent

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 65 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 216,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
-------------------------	-------------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 74 Wallen Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.5  
 General Construction: 1989  
 Storefront Construction:  
 Building Age: 33  
 Vacant: yes ☐ no x other:  
 Assessed Value: 275,700  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
 x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing Good – asphalt shingles

Windows and Doors Excellent

Exterior Walls Excellent – vinyl siding

Porch/Stairs/Deck Good

Foundation Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 75 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 272,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 85 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 279,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Unknown – solar panels cover the roof

Windows and Doors      Good

Exterior Walls            Good

Porch/Stairs/Deck        Excellent

Foundation                Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 92 Wallen Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 198,900  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing Good – asphalt shingles

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 94 Wallen Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no x other:  
 Assessed Value: 199,600  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
 x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good – asphalt shingles

Windows and Doors Excellent

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Excellent – stone

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 95 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 289,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Excellent

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 101 Wallen Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 253,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                              Excellent

Windows and Doors              Excellent

Exterior Walls                    Good

Porch/Stairs/Deck                Good

Foundation                        Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 13 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no x other:  
Assessed Value: 181,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good – vinyl siding
Porch/Stairs/Deck	Unknown
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 19 Lovelace Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 176,000  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good – vinyl siding
Porch/Stairs/Deck	Good
Foundation	Excellent
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 29 Lovelace Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1989  
 Storefront Construction:  
 Building Age: 33  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 201,400  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good – asphalt shingles

Windows and Doors Good

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 39 Lovelace Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no x other:  
 Assessed Value: 290,700  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Good – asphalt shingles

Windows and Doors      Fair – older

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck       Good

Foundation               Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 49 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 205,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

☒ Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good – asphalt shingles
Windows and Doors	Poor – very old with deteriorating trim
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 50 Lovelace Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 350,900  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good – minor stains

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 62 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 280,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Excellent

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 65 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 156,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Good – asphalt shingles

Windows and Doors      Good

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 72 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 363,200  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 82 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 252,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Excellent

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 85 Lovelace Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no x other:  
 Assessed Value: 194,600  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good – asphalt shingles

Windows and Doors Fair – old windows

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 95 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 255,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing                      Good – asphalt shingles

Windows and Doors      Good

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck       Good

Foundation               Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 102 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 279,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – minor moss growth
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 107 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 205,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Excellent – asphalt shingles

Windows and Doors      Good

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck        Excellent

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 112 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 301,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                              Excellent

Windows and Doors              Excellent

Exterior Walls                    Excellent

Porch/Stairs/Deck                Excellent

Foundation                        Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 117 Lovelace Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1988  
 Storefront Construction:  
 Building Age: 34  
 Vacant: yes ☐ no x other:  
 Assessed Value: 291,800  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component                      Condition

Roofing                      Good

Windows and Doors      Fair

Exterior Walls            Good

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 122 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 266,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 127 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no x other:  
Assessed Value: 204,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 132 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 311,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 142 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 272,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Excellent
Exterior Walls	Fair
Porch/Stairs/Deck	Fair – chipped/faded paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 154 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential:  
Stories: 2  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no x other:  
Assessed Value: 348,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Excellent

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 166 Lovelace Lane  
Zoning or Land Use: R-3  
Commercial/Residential:  
Stories: 1  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 212,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Fair – faded
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 83 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1945  
Storefront Construction:  
Building Age: 77  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 262,300  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Fair
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 93 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2020  
Storefront Construction:  
Building Age: 2  
Vacant: yes ☐ no x other:  
Assessed Value: 391,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Excellent

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 98 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 267,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 108 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1949  
Storefront Construction:  
Building Age: 73  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 276,400  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Good – asphalt shingles

Windows and Doors      Fair – old windows

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck        Good – brick

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 116 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1939  
Storefront Construction:  
Building Age: 83  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 188,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                              Unknown

Windows and Doors              Fair – old

Exterior Walls                      Good

Porch/Stairs/Deck                Good

Foundation                        Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 126 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1939  
Storefront Construction:  
Building Age: 83  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 252,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

unknown

Windows and Doors

Fair – old

Exterior Walls

Good – vinyl siding

Porch/Stairs/Deck

Fair – uneven

Foundation

good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 127 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1950  
Storefront Construction:  
Building Age: 72  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 286,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why.	Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 134 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1961  
Storefront Construction:  
Building Age: 61  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 259,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

☒ Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Poor – stains with moss growth

Windows and Doors      Good – new door

Exterior Walls            Fair - stains

Porch/Stairs/Deck       Fair – minor chips

Foundation               Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 135 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1987  
Storefront Construction:  
Building Age: 35  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 352,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 144 South Tessier St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1962  
 Storefront Construction:  
 Building Age: 60  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 248,900  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair - older
Exterior Walls	Fair
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 149 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1954  
Storefront Construction:  
Building Age: 68  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 345,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

☒ Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination

☐ Other (please explain)

☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Poor – missing/damaged siding
Porch/Stairs/Deck	Fair
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 168 South Tessier St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1994  
 Storefront Construction:  
 Building Age: 28  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 386,500  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 190 South Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 258,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Excellent
-------------------	-----------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 201 Tessier Lane  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 2003  
 Storefront Construction:  
 Building Age: 19  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 321,100  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – minor mold growth

Windows and Doors Fair

Exterior Walls Fair

Porch/Stairs/Deck Fair

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 209 Tessier Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 190,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – moss growth

Windows and Doors Fair – old

Exterior Walls Fair – stained

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 213 Tessier Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1952  
Storefront Construction:  
Building Age: 70  
Vacant: yes ☐ no x other:  
Assessed Value: 276,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good – asphalt shingles

Windows and Doors Good

Exterior Walls Excellent – vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 219 Tessier Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 232,300  
Other Relevant Data:

### If the property contributes to slum & blight, please check all that apply.

☒ Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – mold/staining
Windows and Doors	Fair – old style
Exterior Walls	Poor – rotted wood
Porch/Stairs/Deck	Poor – rotted wood
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 221 Tessier Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1925  
Storefront Construction:  
Building Age: 97  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 277,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

☒ Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair
Exterior Walls	Fair – minor chips
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	



Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 234 Tessier Lane  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1985  
Storefront Construction:  
Building Age: 37  
Vacant: yes ☐ no x other:  
Assessed Value: 538,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	



Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 5 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1922  
Storefront Construction:  
Building Age: 100  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 349,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

☒ The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – moss growth and staining

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 21 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 408,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good – asphalt shingles
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Unknown
Foundation	Unknown
Storefront & Signage	

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 29 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no x other:  
Assessed Value: 286,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – some moss growth
Windows and Doors	Fair – older
Exterior Walls	Fair – some staining, vinyl and wood siding
Porch/Stairs/Deck	Fair – concrete railing falling off
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 35 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 292,100  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 44 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 147,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Good – minor moss growth

Windows and Doors      Fair – old

Exterior Walls            Fair – stains, wood siding

Porch/Stairs/Deck       Fair

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 64 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1936  
Storefront Construction:  
Building Age: 86  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 240,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Fair – some staining
Porch/Stairs/Deck	Poor – brick steps uneven and deteriorating
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 67 South Main St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1850  
 Storefront Construction:  
 Building Age: 172  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 198,400  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Poor – cracked siding with stains
Porch/Stairs/Deck	Fair
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 72 South Main St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1910  
Storefront Construction:  
Building Age: 112  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 168,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      n/a

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 75-77 South Main St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1890  
 Storefront Construction:  
 Building Age: 132  
 Vacant: yes ☐ no x other:  
 Assessed Value: 281,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – stains
Windows and Doors	Fair – old windows
Exterior Walls	Good
Porch/Stairs/Deck	Good – deck is in good condition, stairs are uneven
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 145 South Main St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 306,200  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – old
Exterior Walls	Fair – missing siding on roof trim line
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 28 Spring Hill Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1850  
Storefront Construction:  
Building Age: 172  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 471,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – significant staining

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Fair – some chips

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 29 Spring Hill Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1850  
Storefront Construction:  
Building Age: 172  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 335,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – stains and moss growth
Porch/Stairs/Deck	Unknown
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 32 Spring Hill Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1925  
Storefront Construction:  
Building Age: 97  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 283,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Excellent
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 43-45 Spring Hill Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 285,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – missing siding, damaged trim
Porch/Stairs/Deck	Excellent
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 78 Spring Hill Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1949  
Storefront Construction:  
Building Age: 73  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 348,900  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – moss growth and stains

Windows and Doors Fair – older

Exterior Walls Good

Porch/Stairs/Deck Unknown

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 8 Hudson St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1934  
 Storefront Construction:  
 Building Age: 88  
 Vacant: yes ☐ no x other:  
 Assessed Value: 266,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors      Good

Exterior Walls              Good

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 18 Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 270,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older style windows
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: # Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 2022  
Storefront Construction:  
Building Age: >1 year  
Vacant: yes ☐ no ☐ other:  
Assessed Value:  
Other Relevant Data: new construction;  
some data unknown

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Excellent

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: # Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2022  
Storefront Construction:  
Building Age: >1 year  
Vacant: yes ☐ no ☐ other:  
Assessed Value:  
Other Relevant Data: new construction;  
some data unknown

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Excellent
-------------------	-----------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 36 Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1921  
Storefront Construction:  
Building Age: 101  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 240,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Fair – faded paint
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 50 Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1981  
Storefront Construction:  
Building Age: 41  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 385,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – minor staining

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 59-61 Hudson St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 2006  
 Storefront Construction:  
 Building Age: 16  
 Vacant: yes ☐ no x other:  
 Assessed Value: 245,300  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination

☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 62 Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1948  
Storefront Construction:  
Building Age: 74  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 241,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

x Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – stains
Windows and Doors	Fair – old
Exterior Walls	Fair – chipped paint
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 93-95 Hudson St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2006  
Storefront Construction:  
Building Age: 16  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 254,200  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Good
Exterior Walls	Excellent
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 4 North Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1850  
Storefront Construction:  
Building Age: 172  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 265,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 22 North Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1930  
Storefront Construction:  
Building Age: 92  
Vacant: yes ☐ no x other:  
Assessed Value: 293,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – lifting shingles with stains

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 27 North Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1940  
Storefront Construction:  
Building Age: 82  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 297,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 30 North Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1910  
Storefront Construction:  
Building Age: 112  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 211,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

☒ Physical Deterioration of Building

- ☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Poor – significant staining/ mold and moss growth

Windows and Doors      Fair – older style

Exterior Walls            Fair – area of damaged siding

Porch/Stairs/Deck       Fair – damaged wood/chipped paint

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 44 North Tessier St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1875  
 Storefront Construction:  
 Building Age: 147  
 Vacant: yes ☐ no x other:  
 Assessed Value:  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Poor – moss growth with stains

Windows and Doors Fair – older

Exterior Walls Good

Porch/Stairs/Deck Unknown

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 46 North Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1950  
Storefront Construction:  
Building Age: 72  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 189,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Unknown

Windows and Doors                      Unknown

Exterior Walls                      Unknown

Porch/Stairs/Deck                      Unknown

Foundation                      Unknown

Storefront & Signage

Parking Lots

Other: Cannot see house from street

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Unknown



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 50 North Tessier St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1875  
Storefront Construction:  
Building Age: 147  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 323,500  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – no railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 19-21 Elson Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1850  
Storefront Construction:  
Building Age: 172  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 324,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good – minor stains
Windows and Doors	Fair – missing/broken trim
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 27 Elson Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 2018  
 Storefront Construction:  
 Building Age: 4  
 Vacant: yes ☐ no x other:  
 Assessed Value: 424,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
 x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Excellent
-------------------	-----------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 32 Elston Ave  
Zoning or Land Use:  
Commercial/Residential:  
Stories: 1.25  
General Construction: 1937  
Storefront Construction:  
Building Age: 85  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 259,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good – granite stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 50 Elston Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1957  
Storefront Construction:  
Building Age: 65  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 262,200  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair - stains
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 60 Elston Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1950  
 Storefront Construction:  
 Building Age: 72  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 257,800  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing	Fair – stains
Windows and Doors	Fair – old
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Poor – missing siding on porch with hole in the side, stairs are in good condition
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1791 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1960  
Storefront Construction:  
Building Age: 62  
Vacant: yes ☐ no x other:  
Assessed Value: 282,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – stains
Windows and Doors	Fair – old
Exterior Walls	Fair – chipped paint
Porch/Stairs/Deck	Unknown
Foundation	Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1792 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1900  
 Storefront Construction:  
 Building Age: 122  
 Vacant: yes ☐ no x other:  
 Assessed Value: 373,600  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
 x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good – asphalt shingles
Windows and Doors	Good – newer
Exterior Walls	Fair – older wood siding, some chipping
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1799 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1953  
Storefront Construction:  
Building Age: 69  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 298,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good – minor moss growth
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1808 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2.5  
General Construction: 1880  
Storefront Construction:  
Building Age: 142  
Vacant: yes ☐ no x other:  
Assessed Value: 349,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – some staining on door
Exterior Walls	Good
Porch/Stairs/Deck	Fair – some moss growth
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 1819 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1960  
Storefront Construction:  
Building Age: 62  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 291,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing                      Good – asphalt shingles

Windows and Doors      Good

Exterior Walls            Good – aluminum

Porch/Stairs/Deck        Excellent

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1827 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1918  
 Storefront Construction:  
 Building Age: 104  
 Vacant: yes ☐ no x other:  
 Assessed Value: 317,400  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Good

Windows and Doors      Good

Exterior Walls            Good

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 1852 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2018  
Storefront Construction:  
Building Age: 4  
Vacant: yes ☐ no x other:  
Assessed Value: 423,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                              Excellent

Windows and Doors              Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                Excellent

Foundation                        Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1856 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 2019  
 Storefront Construction:  
 Building Age: 3  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 389,700  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                              Excellent

Windows and Doors            Excellent

Exterior Walls                    Excellent

Porch/Stairs/Deck              Excellent

Foundation                        Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 1861-1863 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2019  
Storefront Construction:  
Building Age: 3  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 379,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Excellent
-------------------	-----------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 1874-1876 Providence Rd  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1987  
Storefront Construction:  
Building Age: 35  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 304,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
-------------------------	-------------------------

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Unknown
Foundation	Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 1880 Providence Rd  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1939  
Storefront Construction:  
Building Age: 83  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 340,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Fair – windows are newer, door is stained
Exterior Walls	Good
Porch/Stairs/Deck	Good – stone stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2011 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1927  
Storefront Construction:  
Building Age: 95  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 233,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good – minor stains
Windows and Doors	Fair – old
Exterior Walls	Fair – vinyl siding is stained
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2035 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1987  
Storefront Construction:  
Building Age: 35  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 198,300  
Other Relevant Data:



### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property

### Value

- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

☒ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Fair – brick is stained, minor moss growth

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2040 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1945  
 Storefront Construction:  
 Building Age: 77  
 Vacant: yes ☐ no x other:  
 Assessed Value: 254,100  
 Other Relevant Data: Service Shop

## **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Poor – shingles are falling apart
Windows and Doors	Fair – some newer doors
Exterior Walls	Poor – overgrown ivy, siding is rotting in some spots, chipped paint
Porch/Stairs/Deck	N/a
Foundation	Unknown
Storefront & Signage	Fair
Parking Lots	Poor – missing pavement, potholes
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2043 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Commercial  
Stories: 1  
General Construction: 1940  
Storefront Construction:  
Building Age: 82  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 169,200  
Other Relevant Data: Restaurant/Bar

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	Good
Parking Lots	Fair – no paint
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2106-2108 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 213,300  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – warped and stained in some spots
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 2112 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Commercial  
Stories: 1  
General Construction: 1925  
Storefront Construction:  
Building Age: 97  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 194,700  
Other Relevant Data: unknown business

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	n/a
Foundation	Good
Storefront & Signage	Poor – none
Parking Lots	Poor – uneven with cracks

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2116 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 172,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair
Windows and Doors	Fair – old
Exterior Walls	Fair – old, some rotting around windows
Porch/Stairs/Deck	Fair – stained and corners are chipped
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2120 Providence Rd  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 198,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Good

Windows and Doors

Poor – old

Exterior Walls

Poor – chipped/faded paint

Porch/Stairs/Deck

Good

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2122 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 207,100  
 Other Relevant Data:



## If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – old
Exterior Walls	Good – aluminum
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2128 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 178,600  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good – asphalt shingles
Windows and Doors	Fair – downstairs windows are good, upstairs windows are old
Exterior Walls	Fair – first floor vinyl with some chips, second floor aluminum with stains and worn out
Porch/Stairs/Deck	Fair – old and stained, porch is crooked
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2134 Providence Rd  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2.75  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 289,400  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Fair – crooked
Foundation	Fair - stained
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2138 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1973  
 Storefront Construction:  
 Building Age: 49  
 Vacant: yes ☐ no ☐ other:  
 Assessed Value: 310,000  
 Other Relevant Data: Northbridge  
 Laundromat

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing Good – minor lifting of shingles

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage Fair – sign not visible head on

Parking Lots Fair - cracks

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2147 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Commercial  
Stories: 1  
General Construction: 1930  
Storefront Construction:  
Building Age: 92  
Vacant: yes x no ☐ other:  
Assessed Value: 263,900  
Other Relevant Data: Sammy's  
Restaurant



### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
x Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Poor – moss growth and debris

Windows and Doors Fair

Exterior Walls Poor – broken siding

Porch/Stairs/Deck n/a

Foundation Unknown

Storefront & Signage Fair

Parking Lots Fair – uneven

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2171 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 3  
 General Construction: 1810  
 Storefront Construction:  
 Building Age: 212  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 282,400  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – some warping
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – wood paint is chipped; some siding is warped; wood is worn out
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2177 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1890  
Storefront Construction:  
Building Age: 132  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 93,600  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – old
Exterior Walls	Poor – chipped siding with broken trim
Porch/Stairs/Deck	Poor – uneven and bowed
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2184 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 1.5  
 General Construction: 1917  
 Storefront Construction:  
 Building Age: 105  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 280,600  
 Other Relevant Data:

## If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing Poor – significant moss growth

Windows and Doors Fair – old

Exterior Walls Fair – stains

Porch/Stairs/Deck Fair – moss growth

Foundation Fair – moss growth

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2187 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1900  
 Storefront Construction:  
 Building Age: 122  
 Vacant: yes ☐ no ☐ other:  
 Assessed Value: 242,100  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Fair – old with few cracks
Storefront & Signage	
Parking Lots	

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2191 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 189,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property

#### Value

- ☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Excellent
Porch/Stairs/Deck	Good
Foundation	Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2195 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2.5  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 303,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – siding on side is chipping
Porch/Stairs/Deck	Fair – worn out paint
Foundation	Fair - stains
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2194-2196  
Zoning or Land Use: B-1  
Commercial/Residential: Commercial  
Stories: 1  
General Construction: 1930  
Storefront Construction:  
Building Age: 92  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 232,000  
Other Relevant Data: Service Shop

### **If the property contributes to slum & blight, please check all that apply.**

☒ Physical Deterioration of Building

☐ Abandoned Property

☐ Chronic High Occupancy

Turnover

☐ Chronic High Vacancy Rate

☐ Significant Decline in Property

Value

☐ Abnormally Low Property Value

☐ Known or Suspected

Environmental Contamination

☐ Other (please explain)

☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Unknown

Windows and Doors

Fair – chipped paint

Exterior Walls

Fair – chipped paint

Porch/Stairs/Deck

n/a

Foundation

Good

Storefront & Signage

Poor – no signage

Parking Lots

Poor – cracks, uneven, minor flooding

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2201 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Mixed Use  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 319,000  
Other Relevant Data: Gary's Variety

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – faded siding
Porch/Stairs/Deck	Fair – chipped stairs
Foundation	Good
Storefront & Signage	Fair – excessive signage
Parking Lots	n/a

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2205-2207 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2.75  
General Construction: 1880  
Storefront Construction:  
Building Age: 142  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 421,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – old, some stains
Exterior Walls	Fair – stained
Porch/Stairs/Deck	Fair – chipped paint on railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2208 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1915  
Storefront Construction:  
Building Age: 107  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 540,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – old
Exterior Walls	Fair – aluminum chipped with stains
Porch/Stairs/Deck	Fair
Foundation	Good
Storefront & Signage	
Parking Lots	Poor – dirt
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2209-2211  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 437,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Unknown

Windows and Doors

Fair

Exterior Walls

Fair – stained and chipped

Porch/Stairs/Deck

Fair – paint chipping

Foundation

Fair - stained

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2223-2225 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Mixed Use  
Stories: 3  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 661,800  
Other Relevant Data: Northbridge  
House of Pizza

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – trim is falling off
Exterior Walls	Poor – trim is falling off
Porch/Stairs/Deck	n/a
Foundation	Fair
Storefront & Signage	Good
Parking Lots	Fair – big potholes
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2227 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes x no ☐ other:  
Assessed Value: 90,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
x Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Poor – missing shingles

Windows and Doors Poor – boarded up

Exterior Walls Poor – chipped

Porch/Stairs/Deck n/a

Foundation Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2227R Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 455,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – stucco is stained
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2228-2238 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Commercial  
Stories: 1  
General Construction: 1977  
Storefront Construction:  
Building Age: 45  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 894,700  
Other Relevant Data: Cumberland Farms, vacant business, and a copy business

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	Fair – one sign missing cover

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2233-2235 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1925  
 Storefront Construction:  
 Building Age: 97  
 Vacant: yes ☐ no x other:  
 Assessed Value: 211,100  
 Other Relevant Data: D'Alto Electric

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Excellent
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	Good
Parking Lots	Good – newly paved

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 2239-2247 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1921  
Storefront Construction:  
Building Age: 101  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 693,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing Fair – flat roof, but some signs of wear around trim

Windows and Doors Fair – door is stained, older windows

Exterior Walls Good

Porch/Stairs/Deck Fair – minor stains/weathering

Foundation Fair – some staining and moss growth

Storefront & Signage

Parking Lots Fair – gravel, potholes

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2246 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1775  
 Storefront Construction:  
 Building Age: 247  
 Vacant: yes ☐ no x other:  
 Assessed Value: 226,800  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair
Windows and Doors	Fair – old, one is boarded up on side
Exterior Walls	Poor – side is missing all paint
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2248 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1930  
 Storefront Construction:  
 Building Age: 92  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 136,500  
 Other Relevant Data: Junk in the Trunk

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – paint is chipping around trim
Exterior Walls	Fair – wood siding, stained around side, some chipped paint
Porch/Stairs/Deck	Fair – some stains and signs of wear
Foundation	Good
Storefront & Signage	Fair - small
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 2249 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 563,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Unknown – flat roof
Windows and Doors	Good – newer
Exterior Walls	Good
Porch/Stairs/Deck	Fair – wood on porch is weathered
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2251-2255 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 412,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Unknown – flat roof
Windows and Doors	Fair – old, door is stained
Exterior Walls	Fair – most of first floor is stained
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 2256 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1902  
Storefront Construction:  
Building Age: 120  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 236,200  
Other Relevant Data:



### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property

#### Value

- ☐ Abnormally Low Property Value
- ☐ Known or Suspected

#### Environmental Contamination

- ☐ Other (please explain)

*x The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – damaged concrete steps
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2259 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1870  
Storefront Construction:  
Building Age: 152  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 281,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Unknown – flat roof

Windows and Doors      Fair – old

Exterior Walls            Fair – stained

Porch/Stairs/Deck       Fair – warped, stained, and railings are rusted

Foundation               Fair – some stains, poles holding up bay windows show rust and may not be sturdy

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2264 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1802  
 Storefront Construction:  
 Building Age: 220  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 199,700  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component                      Condition

Roofing                              Unknown

Windows and Doors              Fair – old

Exterior Walls                      Unknown

Porch/Stairs/Deck                Good

Foundation                        Unknown

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2270-2276 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2.5  
General Construction: 1880  
Storefront Construction:  
Building Age: 142  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 353,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2273-2277 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1927  
 Storefront Construction:  
 Building Age: 95  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 260,500  
 Other Relevant Data: The Beauty Call

## If the property contributes to slum & blight, please check all that apply.

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – right side are old
Exterior Walls	Fair – minor stains
Porch/Stairs/Deck	Fair – steps are stained and crooked
Foundation	Good
Storefront & Signage	Fair – small and not visible head on
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2279-2283 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Mixed Use  
 Stories: 2  
 General Construction: 1937  
 Storefront Construction:  
 Building Age: 85  
 Vacant: yes x no ☐ other:  
 Assessed Value: 396,100  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair - old
Exterior Walls	Poor – some lifting siding, trim is rotting
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	Fair
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2282-2288 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1880  
 Storefront Construction:  
 Building Age: 142  
 Vacant: yes ☐ no x other:  
 Assessed Value: 473,100  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 2285-2291 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1902  
Storefront Construction:  
Building Age: 120  
Vacant: yes x no ☐ other:  
Assessed Value: 386,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing Fair – asphalt shingles, some warping

Windows and Doors Good

Exterior Walls Fair – some stains

Porch/Stairs/Deck Fair – steps are stained

Foundation Fair – few cracks

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2293-2295 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1902  
Storefront Construction:  
Building Age: 120  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 264,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – some shingles lifting
Windows and Doors	Fair – some trim is stained, older style
Exterior Walls	Fair – some stains
Porch/Stairs/Deck	Fair – railings coming loose, stained steps
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2294 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1849  
Storefront Construction:  
Building Age: 173  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 214,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2297-2299 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2.75  
General Construction: 1890  
Storefront Construction:  
Building Age: 132  
Vacant: yes ☐ no x other:  
Assessed Value: 400,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – some spots chipped or stained
Porch/Stairs/Deck	Good
Foundation	Fair – some moss and stains
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 2305 Providence Rd  
 Zoning or Land Use: B-1  
 Commercial/Residential: Public  
 Stories: 1  
 General Construction: 1940  
 Storefront Construction:  
 Building Age: 82  
 Vacant: yes ☐ no x other:  
 Assessed Value: 240,900  
 Other Relevant Data: Fire Station

## If the property contributes to slum & blight, please check all that apply.

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Poor – trim is weathered, stained brick
Porch/Stairs/Deck	n/a
Foundation	Good
Storefront & Signage	Fair – signs are very weathered
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 2311-2317 Providence Rd  
Zoning or Land Use: B-1  
Commercial/Residential: Commercial  
Stories: 1  
General Construction: 1944  
Storefront Construction:  
Building Age: 78  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 287,500  
Other Relevant Data: Gas Station

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair
Porch/Stairs/Deck	n/a
Foundation	Fair – weathered, stains, minor growth
Storefront & Signage	Fair – minimal signage
Parking Lots	Fair – some cracks
Other:	
Overall Property Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 10-12 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 366,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Poor – significant moss growth

Windows and Doors      Good

Exterior Walls            Fair – moss

Porch/Stairs/Deck       Fair – worn paint

Foundation               Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 20 Upton St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1875  
 Storefront Construction:  
 Building Age: 147  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 204,700  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – old
Exterior Walls	Poor – very stained
Porch/Stairs/Deck	Poor – broken stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 24 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 202,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Poor – stains, moss
Windows and Doors	Poor – old, broken windows
Exterior Walls	Fair
Porch/Stairs/Deck	Poor – no railings
Foundation	Poor
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 28-30 Upton St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1910  
 Storefront Construction:  
 Building Age: 112  
 Vacant: yes ☐ no x other:  
 Assessed Value: 334,100  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good – vinyl siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 36-38 Upton St  
Zoning or Land Use: -3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1890  
Storefront Construction:  
Building Age: 132  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 238,400  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – stains
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 42-44 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 228,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good

Windows and Doors	Fair – old
-------------------	------------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 50-52 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 242,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good – asphalt shingles
Windows and Doors	Fair – old
Exterior Walls	Poor – severely damaged siding and trim
Porch/Stairs/Deck	Poor – overgrown
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 58-60 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 283,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Poor – lifting shingles and stains

Windows and Doors      Fair – old

Exterior Walls            Good – vinyl siding

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 59-61 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 276,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 67-69 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 280,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 79-81 Upton St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 258,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 26 Emond St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 389,500  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – minor stains
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 35 Emond St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no x other:  
Assessed Value: 284,800  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good – asphalt shingles

Windows and Doors Good

Exterior Walls Excellent – vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 43 Emond St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1922  
 Storefront Construction:  
 Building Age: 100  
 Vacant: yes x no ☐ other:  
 Assessed Value: 235,600  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- x Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – overgrown, stained
Windows and Doors	Poor – broken, paint is chipping on door, stained
Exterior Walls	Poor – wood siding, paint is very chipped, overgrown with vines
Porch/Stairs/Deck	Fair – overgrown
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor	



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 53 Emond St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.5  
 General Construction: 1965  
 Storefront Construction:  
 Building Age: 57  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 245,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Poor – moss and stained

Windows and Doors Fair – old

Exterior Walls Good – aluminum siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 58 Emond St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1925  
Storefront Construction:  
Building Age: 97  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 291,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Good
Exterior Walls	Excellent
Porch/Stairs/Deck	Good
Foundation	Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 5-7 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1909  
 Storefront Construction:  
 Building Age: 113  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 292,700  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – stains
Windows and Doors	Fair – old
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Fair –weathered
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 9-11 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 189,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair
Exterior Walls	Fair – deteriorating trim
Porch/Stairs/Deck	Fair – weathered wood
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 17 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 227,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Roofing	Good
Windows and Doors	Fair – older style
Exterior Walls	Good
Porch/Stairs/Deck	Unknown
Foundation	Unknown
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 25-27 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1909  
 Storefront Construction:  
 Building Age: 113  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 273,800  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing Fair – trim is stained

Windows and Doors Fair - old

Exterior Walls Good

Porch/Stairs/Deck Fair – old, stained

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 35-37 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 170,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Fair – siding is lifting
Porch/Stairs/Deck	Fair – weathered/stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 43-45 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 309,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Excellent
Windows and Doors	Fair – older style
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 51-53 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1892  
Storefront Construction:  
Building Age: 130  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 267,800  
Other Relevant Data:



### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 63 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1986  
Storefront Construction:  
Building Age: 36  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 2,467,900  
Other Relevant Data: Rockdale House

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	Good
----------------------	------

Parking Lots	Good
--------------	------

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 72-76 School St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no x other:  
Assessed Value:  
Other Relevant Data:



### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 77-79 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2.5  
 General Construction: 1890  
 Storefront Construction:  
 Building Age: 132  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 323,600  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 80 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Mixed Use  
 Stories: 1.75  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 315,700  
 Other Relevant Data: Turgeon Funeral Home

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good – asphalt shingles
Windows and Doors	Good
Exterior Walls	Fair – side walls have chipped paint
Porch/Stairs/Deck	Fair – Front porch is good, but side balcony is poor, rotting and chipped
Foundation	Good
Storefront & Signage	Fair – only one small sign
Parking Lots	Fair – pavement is worn

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 85 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1945  
 Storefront Construction:  
 Building Age: 77  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 331,400  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Poor – wood siding, chipped paint, stains
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 90 School St  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1870  
 Storefront Construction:  
 Building Age: 152  
 Vacant: yes ☐ no x other:  
 Assessed Value: 296,500  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – old
Windows and Doors	Fair – old style
Exterior Walls	Fair – some stains, shudders are faded
Porch/Stairs/Deck	Fair – minor stains
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	




# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 91-97 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1915  
 Storefront Construction:  
 Building Age: 107  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 728,500  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair - faded
Porch/Stairs/Deck	Fair – chipped wood
Foundation	Fair - stained
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 98-100 School St  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 3  
 General Construction: 1897  
 Storefront Construction:  
 Building Age: 125  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 436,800  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – stained
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	Fair – some potholes
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 103-107 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 3  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 344,400  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – older, some wear on trim
Exterior Walls	Fair – some vines
Porch/Stairs/Deck	Fair – upper decks are weathered and slanted
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	Fair – pavement is worn and cracked
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 106-108 School St  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 2.5  
 General Construction: 1880  
 Storefront Construction:  
 Building Age: 142  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 419,900  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Good
Foundation	Fair – cracks and moss
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 109-113 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1926  
Storefront Construction:  
Building Age: 96  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 379,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good – vinyl siding
Porch/Stairs/Deck	Good
Foundation	Fair – some signs of wear
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 117 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1954  
Storefront Construction:  
Building Age: 68  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 251,600  
Other Relevant Data: completely invisible from street

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Unknown
---------	---------

Windows and Doors	Unknown
-------------------	---------

Exterior Walls	Unknown
----------------	---------

Porch/Stairs/Deck	Unknown
-------------------	---------

Foundation	Unknown
------------	---------

Storefront & Signage

Parking Lots

Other: completely invisible from street view

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Unknown



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 119-125 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1935  
Storefront Construction:  
Building Age: 87  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 639,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing Fair – some wear

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 127 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1953  
Storefront Construction:  
Building Age: 69  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 325,600  
Other Relevant Data: completely  
invisible from street

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
-------------------------	-------------------------

Roofing	Unknown
---------	---------

Windows and Doors	Unknown
-------------------	---------

Exterior Walls	Unknown
----------------	---------

Porch/Stairs/Deck	Unknown
-------------------	---------

Foundation	Unknown
------------	---------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other: completely  
invisible from street  
view

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Unknown

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 132 School St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1909  
Storefront Construction:  
Building Age: 113  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 272,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Fair – significant staining
Windows and Doors	Fair – older style
Exterior Walls	Poor – worn paint/damaged
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 133 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1942  
Storefront Construction:  
Building Age: 80  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 211,700  
Other Relevant Data: completely invisible from street

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Unknown
---------	---------

Windows and Doors	Unknown
-------------------	---------

Exterior Walls	Unknown
----------------	---------

Porch/Stairs/Deck	Unknown
-------------------	---------

Foundation	Unknown
------------	---------

Storefront & Signage

Parking Lots

Other: completely invisible from street

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Unknown

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 139 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1939  
Storefront Construction:  
Building Age: 83  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 384,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                              Excellent

Windows and Doors              Good

Exterior Walls                    Excellent

Porch/Stairs/Deck                Good

Foundation                        Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 142 School St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1940  
Storefront Construction:  
Building Age: 82  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 279,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – older style
Exterior Walls	Fair – staining present
Porch/Stairs/Deck	Poor – no railings, damaged concrete
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 145-147 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2.5  
General Construction: 1930  
Storefront Construction:  
Building Age: 92  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 363,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good – minor stains
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – porch in good condition, stairs are worn and stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 150-152 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1870  
Storefront Construction:  
Building Age: 152  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 219,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Poor – significant moss growth (side), damaged shingles

Windows and Doors      Poor – old/damaged windows

Exterior Walls            Fair – areas of damaged siding

Porch/Stairs/Deck       Fair

Foundation               Fair

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 153-157 School St  
Zoning or Land Use: R-1  
Commercial/Residential: Residential  
Stories: 2.5  
General Construction: 1910  
Storefront Construction:  
Building Age: 112  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 120,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – stains
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – weathered, chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 166 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1957  
Storefront Construction:  
Building Age: 65  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 265,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – stains
Windows and Doors	Fair – older style
Exterior Walls	Fair – damaged siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 174 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1948  
 Storefront Construction:  
 Building Age: 74  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 237,700  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 175 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2004  
Storefront Construction:  
Building Age: 18  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 463,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 187 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1934  
Storefront Construction:  
Building Age: 88  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 376,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing                      Excellent – asphalt shingles

Windows and Doors      Good

Exterior Walls            Good – brick and stucco

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 190 School St  
Zoning or Land Use: R-3  
Commercial/Residential:  
Stories: 1.5  
General Construction: 1948  
Storefront Construction:  
Building Age: 74  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 253,100  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 205 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1975  
Storefront Construction:  
Building Age: 47  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 284,000  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older style
Exterior Walls	Good
Porch/Stairs/Deck	Fair – some wear on porch
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 206-208 School St  
Zoning or Land Use: R-3  
Commercial/Residential:  
Stories: 1.75  
General Construction: 1903  
Storefront Construction:  
Building Age: 119  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 399,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – moss growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Excellent

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 213 School St  
Zoning or Land Use:  
Commercial/Residential:  
Stories: 1.75  
General Construction: 1945  
Storefront Construction:  
Building Age: 77  
Vacant: yes ☐ no x other:  
Assessed Value: 297,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Excellent
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 224 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1922  
 Storefront Construction:  
 Building Age: 100  
 Vacant: yes ☐ no x other:  
 Assessed Value: 254,500  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Fair – uneven bricks
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 227 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1932  
Storefront Construction:  
Building Age: 90  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 293,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – chipped paint
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 236 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.5  
 General Construction: 1909  
 Storefront Construction:  
 Building Age: 113  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 289,600  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component

## Condition

Roofing Fair – moss growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 239 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1953  
Storefront Construction:  
Building Age: 69  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 233,000  
Other Relevant Data:

### If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 254 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1969  
Storefront Construction:  
Building Age: 53  
Vacant: yes ☐ no x other:  
Assessed Value: 306,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – minor staining/mold growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 260 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1966  
Storefront Construction:  
Building Age: 56  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 254,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – old windows, new door
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 267 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1978  
Storefront Construction:  
Building Age: 44  
Vacant: yes ☐ no x other:  
Assessed Value: 280,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 268/272 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1780/1982  
Storefront Construction:  
Building Age: 242/40  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 545,600  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Poor – moss growth and stains

Windows and Doors      Fair – old

Exterior Walls            Good

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 281 School St  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1948  
Storefront Construction:  
Building Age: 74  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 236,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Excellent

Windows and Doors                      Excellent

Exterior Walls                      Excellent

Porch/Stairs/Deck                      Good

Foundation                      Excellent

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 296 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1965  
 Storefront Construction:  
 Building Age: 57  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 248,200  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

## Component                      Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 306 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1972  
Storefront Construction:  
Building Age: 50  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 280,500  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good – wood siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 316 School St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1950  
Storefront Construction:  
Building Age: 72  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 241,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – stained
Windows and Doors	Fair – older style
Exterior Walls	Good
Porch/Stairs/Deck	Fair – awning is rusted and deteriorating
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 338 School St  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1875  
 Storefront Construction:  
 Building Age: 147  
 Vacant: yes ☐ no x other:  
 Assessed Value: 269,700  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – asphalt shingles
Windows and Doors	Fair – older
Exterior Walls	Good – newly painted wood siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 28-30 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 225,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Unknown – solar panels (hard to see)

Windows and Doors Fair – older

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 34-36 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 273,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older style, trim is chipping
Exterior Walls	Good
Porch/Stairs/Deck	Fair – some moss growth and stains
Foundation	Fair - stains
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 38-40 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 218,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair - older
Exterior Walls	Fair – aluminum siding is chipping
Porch/Stairs/Deck	Fair
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 39 Church Ave  
 Zoning or Land Use: R-5  
 Commercial/Residential:  
 Public/Institutional  
 Stories:  
 General Construction:  
 Storefront Construction:  
 Building Age:  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value:  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
 x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	Good
Parking Lots	Good

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 44-46 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2016  
Storefront Construction:  
Building Age: 6  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 237,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 50-52 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 250,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – stains
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 56-58 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 212,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Poor – a lot of stains
Windows and Doors	Fair – old
Exterior Walls	Poor – discoloration, rust
Porch/Stairs/Deck	Fair
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 60-62 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 226,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – some shingles lifting, deteriorating trim

Windows and Doors Fair – older

Exterior Walls Poor – peeling paint

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 66-68 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 244,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Fair – trim is stained and chipping
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 72-74 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 219,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Poor – old, trim is rotting
Exterior Walls	Poor – wood siding, mostly chipped
Porch/Stairs/Deck	Good
Foundation	Fair – stained
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 76-78 Church Ave  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 1900  
 General Construction: 1900  
 Storefront Construction:  
 Building Age: 122  
 Vacant: yes ☐ no x other:  
 Assessed Value: 223,300  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good – wood siding
Porch/Stairs/Deck	Fair – brick steps, railings are crooked
Foundation	Fair – stained
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 82-84 Church Ave  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1900  
 Storefront Construction:  
 Building Age: 122  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 263,800  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – minor stains
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 85 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 1,441,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Unknown
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – wood is slanted and weathered
Foundation	Fair – some stains
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 90-96 Church Ave  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1903  
 Storefront Construction:  
 Building Age: 119  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 542,500  
 Other Relevant Data:

## **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – asphalt shingles
Windows and Doors	Fair – old
Exterior Walls	Poor – stained, chipped, overgrown ivy
Porch/Stairs/Deck	Poor – chipped paint
Foundation	Fair - stained
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 95 Church Ave  
Zoning or Land Use: B-1  
Commercial/Residential: Commercial  
Stories: 2  
General Construction: 1905  
Storefront Construction:  
Building Age: 117  
Vacant: yes x no ☐ other:  
Assessed Value: 316,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
x Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Unknown
Windows and Doors	Fair
Exterior Walls	Poor – holes near bottom
Porch/Stairs/Deck	n/a
Foundation	Fair
Storefront & Signage	Poor – no signage
Parking Lots	

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 99-103 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1903  
Storefront Construction:  
Building Age: 119  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 274,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 104-106 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☐ other:  
Assessed Value: 296,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – dirty siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 116-118 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 303,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – paint on shutters is faded
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 125-127 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1902  
Storefront Construction:  
Building Age: 120  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 275,900  
Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – minor stains

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 133-135 Church Ave  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1902  
Storefront Construction:  
Building Age: 120  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 129,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 177 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1954  
Storefront Construction:  
Building Age: 68  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 253,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Excellent – new windows
Exterior Walls	Good
Porch/Stairs/Deck	Fair – uneven stairs
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 191 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1962  
Storefront Construction:  
Building Age: 60  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 344,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 198 Church Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1960  
 Storefront Construction:  
 Building Age: 62  
 Vacant: yes ☐ no x other:  
 Assessed Value: 643,600  
 Other Relevant Data: Northbridge TV

## **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	n/a
Foundation	Good
Storefront & Signage	Poor – small, no sign on street
Parking Lots	Good
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 200 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1989  
Storefront Construction:  
Building Age: 33  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 444,200  
Other Relevant Data: cannot see from street

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Windows and Doors

Exterior Walls

Porch/Stairs/Deck

Foundation

Storefront & Signage

Parking Lots

Other: cannot see from street

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Unknown



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 203 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1963  
Storefront Construction:  
Building Age: 59  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 236,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 204 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1966  
Storefront Construction:  
Building Age: 56  
Vacant: yes ☐ no x other:  
Assessed Value: 283,000  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- x ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – a lot of stains

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 214 Church Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1966  
 Storefront Construction:  
 Building Age: 56  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 250,800  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing Fair – stained

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 217 Church Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1967  
 Storefront Construction:  
 Building Age: 55  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 265,300  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 226 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1966  
Storefront Construction:  
Building Age: 56  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 261,100  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 227 Church Ave  
Zoning or Land Use: R-2  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1932  
Storefront Construction:  
Building Age: 90  
Vacant: yes ☐ no x other:  
Assessed Value: 281,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – stains/moss on side

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 234 Church Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1967  
 Storefront Construction:  
 Building Age: 55  
 Vacant: yes ☐ no x other:  
 Assessed Value: 249,900  
 Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 241 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1966  
Storefront Construction:  
Building Age: 56  
Vacant: yes ☐ no x other:  
Assessed Value: 276,000  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing                      Excellent – new asphalt shingles

Windows and Doors      Good

Exterior Walls            Good

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

# 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

## Property Data

Address: 242 Church Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1967  
 Storefront Construction:  
 Building Age: 55  
 Vacant: yes ☐ no x other:  
 Assessed Value: 284,900  
 Other Relevant Data:

If the property contributes to slum & blight, please check all that apply.

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 249 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1966  
Storefront Construction:  
Building Age: 56  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 274,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – aluminum siding with minor chips
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 256 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1967  
Storefront Construction:  
Building Age: 55  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 273,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 261 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1968  
Storefront Construction:  
Building Age: 54  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 279,700  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Poor – very old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 266 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1969  
Storefront Construction:  
Building Age: 53  
Vacant: yes ☐ no x other:  
Assessed Value: 240,500  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 269 Church Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1962  
 Storefront Construction:  
 Building Age: 60  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 262,200  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – few missing shingles

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 276 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1967  
Storefront Construction:  
Building Age: 55  
Vacant: yes ☐ no x other:  
Assessed Value: 256,300  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 284 Church Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1968  
Storefront Construction:  
Building Age: 54  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 264,800  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 15 Duggan Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1967  
Storefront Construction:  
Building Age: 55  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 244,200  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
-------------------------	-------------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 16 Duggan Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1967  
Storefront Construction:  
Building Age: 55  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 329,400  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing Fair – minor moss growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 21 Duggan Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1969  
Storefront Construction:  
Building Age: 53  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 292,600  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Good

Windows and Doors

Fair – older style

Exterior Walls

Good – vinyl siding

Porch/Stairs/Deck

Good

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 46 Duggan Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1966  
Storefront Construction:  
Building Age: 56  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 246,300  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Excellent
---------	-----------

Windows and Doors	Excellent
-------------------	-----------

Exterior Walls	Excellent
----------------	-----------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Excellent
------------	-----------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Excellent

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 47 Duggan Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1962  
Storefront Construction:  
Building Age: 60  
Vacant: yes ☐ no x other:  
Assessed Value: 268,800  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 15 Legion Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1959  
 Storefront Construction:  
 Building Age: 63  
 Vacant: yes ☐ no x other:  
 Assessed Value: 361,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 20 Legion Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1968  
Storefront Construction:  
Building Age: 54  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 238,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – stains and moss growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 23 Legion Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1985  
Storefront Construction:  
Building Age: 37  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 370,900  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:	
--------	--

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 28 Legion Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1996  
Storefront Construction:  
Building Age: 26  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 369,700  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Fair – minor stains

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 31 Legion Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1972  
Storefront Construction:  
Building Age: 50  
Vacant: yes ☐ no x other:  
Assessed Value: 266,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage	
----------------------	--

Parking Lots	
--------------	--

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 45 Legion Way  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1987  
 Storefront Construction:  
 Building Age: 35  
 Vacant: yes ☐ no x other:  
 Assessed Value: 291,300  
 Other Relevant Data:



**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing Fair – stains and minor moss growth

Windows and Doors Good

Exterior Walls Good – vinyl siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 63 Legion Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1986  
Storefront Construction:  
Building Age: 36  
Vacant: yes ☐ no x other:  
Assessed Value: 268,800  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component                      Condition

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 64 Legion Way  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1987  
Storefront Construction:  
Building Age: 35  
Vacant: yes ☐ no x other:  
Assessed Value: 338,800  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 4 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1949  
Storefront Construction:  
Building Age: 73  
Vacant: yes ☐ no x other:  
Assessed Value: 328,700  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 7 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1950  
Storefront Construction:  
Building Age: 72  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 294,700  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 16 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1958  
Storefront Construction:  
Building Age: 64  
Vacant: yes ☐ no x other:  
Assessed Value: 230,200  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
  - ☐ Chronic High Occupancy Turnover
  - ☐ Chronic High Vacancy Rate
  - ☐ Significant Decline in Property Value
  - ☐ Abnormally Low Property Value
  - ☐ Known or Suspected Environmental Contamination
  - ☐ Other (please explain)
  - ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing	Poor – a lot of staining
Windows and Doors	Good
Exterior Walls	Fair – a lot of staining with vines
Porch/Stairs/Deck	Unknown
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### **Property Data**

Address: 17 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1951  
Storefront Construction:  
Building Age: 71  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 235,600  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### **Component**

#### **Condition**

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – faded paint
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### **Property Data**

Address: 24 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1954  
Storefront Construction:  
Building Age: 68  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 288,100  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### **Component**

#### **Condition**

Roofing Fair – stains

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 29 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1952  
Storefront Construction:  
Building Age: 70  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 247,800  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing	Good – asphalt shingles
Windows and Doors	Fair – older style
Exterior Walls	Good – vinyl siding
Porch/Stairs/Deck	Fair – minor chips in cement
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 34 Arrowhead Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 1.5  
 General Construction: 1957  
 Storefront Construction:  
 Building Age: 65  
 Vacant: yes ☐ no x other:  
 Assessed Value: 250,600  
 Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Poor – significant moss growth
Windows and Doors	Fair – older
Exterior Walls	Fair – faded paint with stains
Porch/Stairs/Deck	Poor – stains, chipped paint
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 38 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1939  
Storefront Construction:  
Building Age: 83  
Vacant: yes ☐ no x other:  
Assessed Value: 260,000  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### **Property Data**

Address: 41 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1955  
Storefront Construction:  
Building Age: 67  
Vacant: yes ☐ no x other:  
Assessed Value: 316,000  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### **Component**

#### **Condition**

Roofing Fair – stains

Windows and Doors Fair

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 44-46 Arrowhead Ave  
 Zoning or Land Use: R-3  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1986  
 Storefront Construction:  
 Building Age: 36  
 Vacant: yes ☐ no x other:  
 Assessed Value: 169,000  
 Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing Fair – significant staining/moss growth

Windows and Doors Good

Exterior Walls Fair – mold growth present

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 52 Arrowhead Ave  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1956  
Storefront Construction:  
Building Age: 66  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 234,400  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – faded/chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 13 Plantation St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1956  
Storefront Construction:  
Building Age: 66  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 208,400  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing Fair – staining present

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 19 Plantation St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1952  
Storefront Construction:  
Building Age: 70  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 243,700  
Other Relevant Data:

#### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

#### Component

#### Condition

Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – damaged siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



### 3. NAME OF SLUM & BLIGHT AREA: ROCKDALE

#### Property Data

Address: 35 Plantation St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1923  
Storefront Construction:  
Building Age: 99  
Vacant: yes ☐ no x other:  
Assessed Value: 214,200  
Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)

x The property is not contributing to slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
------------------	------------------

Roofing	Good
---------	------

Windows and Doors	Good
-------------------	------

Exterior Walls	Good
----------------	------

Porch/Stairs/Deck	Good
-------------------	------

Foundation	Good
------------	------

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 46-50 Plantation St

Zoning or Land Use: R-5

Commercial/Residential:

Stories: 3

General Construction:

Storefront Construction:

Building Age:

Vacant: yes ☐ no ☐ other:

Assessed Value:

Other Relevant Data:

**If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing

Unknown

Windows and Doors

Fair – older

Exterior Walls

Good

Porch/Stairs/Deck

Fair – chipped paint

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 51 Plantation St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1945  
Storefront Construction:  
Building Age: 77  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 279,500  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 56-58 Plantation St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction:  
Storefront Construction:  
Building Age:  
Vacant: yes ☐ no ☒ other:  
Assessed Value:  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 61 Plantation St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1942  
Storefront Construction:  
Building Age: 80  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 232,600  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing	Fair – minor stains
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 69 Plantation St  
Zoning or Land Use: R-3  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1950  
Storefront Construction:  
Building Age: 72  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 256,100  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing Fair – stains with minor moss growth

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### Property Data

Address: 9-11 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2.75  
General Construction: 1905  
Storefront Construction:  
Building Age: 117  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 358,800  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### Component

##### Condition

Roofing Fair – damaged/missing shingles

Windows and Doors Good

Exterior Walls Fair – faded/worn paint

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 4-12 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 2005  
Storefront Construction:  
Building Age: 17  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 203,400  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 15-19 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1915  
Storefront Construction:  
Building Age: 107  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 549,900  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination

☐ Other (please explain)

☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing Unknown

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 20 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1977  
Storefront Construction:  
Building Age: 45  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 278,300  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing	Good
Windows and Doors	Fair – older style windows
Exterior Walls	Good
Porch/Stairs/Deck	Poor – damaged railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 5. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 30 Taft St  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 1.75  
 General Construction: 1930  
 Storefront Construction:  
 Building Age: 92  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 248,600  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair – minor stains
Windows and Doors	Fair – damaged screens, older style windows
Exterior Walls	Fair – paint worn
Porch/Stairs/Deck	Fair – no railings
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 34-40 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 312,600  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 37-47 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories:  
General Construction:  
Storefront Construction:  
Building Age:  
Vacant: yes ☐ no ☐ other:  
Assessed Value:  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### Property Data

Address: 42-48 Taft St  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 293,400  
 Other Relevant Data:



##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### Component                      Condition

Roofing                      Good

Windows and Doors      Good

Exterior Walls            Good

Porch/Stairs/Deck        Good

Foundation                Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 49-59 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1905  
Storefront Construction:  
Building Age: 117  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 442,900  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 86 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1910  
Storefront Construction:  
Building Age: 112  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 243,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**

### **Condition**

Roofing	Fair – stains
Windows and Doors	Fair – trim is stained
Exterior Walls	Fair – stained
Porch/Stairs/Deck	Fair – stained, stairs are crooked and worn
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 2. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 94 Taft St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1988  
Storefront Construction:  
Building Age: 34  
Vacant: yes ☐ no x other:  
Assessed Value: 271,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – stains
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### Property Data

Address: 4-6 McBride St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1921  
Storefront Construction:  
Building Age: 101  
Vacant: yes ☐ no ☒ other:  
Assessed Value:  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### Component

##### Condition

Roofing

Unknown

Windows and Doors

Fair – older

Exterior Walls

Good

Porch/Stairs/Deck

Fair – chipped paint

Foundation

Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### **Property Data**

Address: 12-14 McBride St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1921  
Storefront Construction:  
Building Age: 101  
Vacant: yes ☐ no ☒ other:  
Assessed Value:  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### **Component**

##### **Condition**

Roofing	Unknown
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 15-21 McBride St  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1922  
 Storefront Construction:  
 Building Age: 100  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 410,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – stained
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### Property Data

Address: 18-20 McBride St  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 3  
General Construction: 1921  
Storefront Construction:  
Building Age: 101  
Vacant: yes ☐ no ☒ other:  
Assessed Value:  
Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

##### Component

##### Condition

Roofing	Unknown
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Fair – minor chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



#### 4. NAME OF SLUM & BLIGHT AREA: ROCKDALE

##### Property Data

Address: 11-13 Cross Place  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 2  
 General Construction: 1905  
 Storefront Construction:  
 Building Age: 117  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 257,900  
 Other Relevant Data:

##### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – damaged screens
Exterior Walls	Good
Porch/Stairs/Deck	Fair – stairs are stained and have minor moss growth
Foundation	Fair – stains and moss growth
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 17-19 Cross Place  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 2.75  
 General Construction: 1912  
 Storefront Construction:  
 Building Age: 110  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 550,500  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – siding is warping near foundation
Porch/Stairs/Deck	Fair – poles holding up deck are rusted, wood is worn
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 23 Cross Place  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2.75  
General Construction: 1912  
Storefront Construction:  
Building Age: 110  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 274,000  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Good
Porch/Stairs/Deck	Poor – wood on deck is worn, stairs are crooked
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 29-31 Cross Place  
 Zoning or Land Use: R-5  
 Commercial/Residential: Residential  
 Stories: 3  
 General Construction: 1885  
 Storefront Construction:  
 Building Age: 137  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 505,900  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Fair – siding is stained
Porch/Stairs/Deck	Poor – all porches are worn and weathered, some are stained
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 4-6 Beanes Lane  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1913  
Storefront Construction:  
Building Age: 109  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 226,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Fair
Windows and Doors	Poor – old windows
Exterior Walls	Poor – faded/chipped paint, missing siding
Porch/Stairs/Deck	Poor – chipped paint, worn wood
Foundation	Fair
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 8 Beanes Lane  
Zoning or Land Use: B-1  
Commercial/Residential: Residential  
Stories:  
General Construction: 1969  
Storefront Construction:  
Building Age: 53  
Vacant: yes ☐ no x other:  
Assessed Value:  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Unknown
Windows and Doors	Fair – old
Exterior Walls	Poor – chipped/faded siding
Porch/Stairs/Deck	Fair – stained
Foundation	Unknown
Storefront & Signage	
Parking Lots	

Other: House is set far back from street

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 12 Beanes Lane  
 Zoning or Land Use: B-1  
 Commercial/Residential: Commercial  
 Stories: 1  
 General Construction: 1950  
 Storefront Construction:  
 Building Age: 72  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 180,700  
 Other Relevant Data: Kim's Tailor/Dry Cleaners



**If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*

Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Fair - stained
Storefront & Signage	Fair – excessive signage
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 22 Beanes Lane  
Zoning or Land Use: B-1  
Commercial/Residential: Mixed Use  
Stories: 2  
General Construction: 1931  
Storefront Construction:  
Building Age: 91  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 460,500  
Other Relevant Data: Stan's Appliances

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Unknown
Windows and Doors	Fair – some older
Exterior Walls	Fair – damaged/dirty siding
Porch/Stairs/Deck	Fair – chipped paint
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 25 Beanes Lane  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1949  
Storefront Construction:  
Building Age: 73  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 233,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building
- ☐ Abandoned Property
- ☐ Chronic High Occupancy Turnover
- ☐ Chronic High Vacancy Rate
- ☐ Significant Decline in Property Value
- ☐ Abnormally Low Property Value
- ☐ Known or Suspected Environmental Contamination
- ☐ Other (please explain)
- ☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Good
Windows and Doors	Fair – older style windows
Exterior Walls	Fair – dirty siding
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 28-30 Beanes Lane  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2.25  
General Construction: 1941  
Storefront Construction:  
Building Age: 81  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 327,400  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Good

Windows and Doors Good

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 29-31 Beanes lane  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1963  
Storefront Construction:  
Building Age: 59  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 712,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Unknown – flat roof

Windows and Doors Good

Exterior Walls Fair – dirty siding

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 35 Beanes Lane  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1  
General Construction: 1933  
Storefront Construction:  
Building Age: 89  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 246,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – vinyl siding is good, garage door is worn and chipping
Porch/Stairs/Deck	Fair – steps are chipped and worn
Foundation	Fair – minor stains
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 36 Beanes Lane  
Zoning or Land Use: R-5  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1939  
Storefront Construction:  
Building Age: 83  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 283,500  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☒ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Fair – stains and minor moss growth
Windows and Doors	Fair – old
Exterior Walls	Good
Porch/Stairs/Deck	Fair – stairs by road are very uneven, some missing
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 4 Central Ave  
Zoning or Land Use: B-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1920  
Storefront Construction:  
Building Age: 102  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 217,100  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      Good

Windows and Doors                      Good

Exterior Walls                      Good

Porch/Stairs/Deck                      Good

Foundation                      Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 9-11 Central Ave  
Zoning or Land Use: B-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1940  
Storefront Construction:  
Building Age: 82  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 294,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing Unknown – flat roof

Windows and Doors Fair – old

Exterior Walls Good

Porch/Stairs/Deck Good

Foundation Good

Storefront & Signage

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 7 Cottage St  
Zoning or Land Use: B-2  
Commercial/Residential: Residential  
Stories: 1.75  
General Construction: 1915  
Storefront Construction:  
Building Age: 107  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 222,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- x Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component

### Condition

Roofing	Excellent
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Poor – side stairs are crumbling
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 8 First Ave  
 Zoning or Land Use: B-2  
 Commercial/Residential: Residential  
 Stories: 1  
 General Construction: 1920  
 Storefront Construction:  
 Building Age: 102  
 Vacant: yes ☐ no ☒ other:  
 Assessed Value: 192,800  
 Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – siding is stained
Porch/Stairs/Deck	Fair – paint is chipped around the base
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 16 First Ave  
Zoning or Land Use: B-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 259,600  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)

x *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Excellent
Windows and Doors	Excellent
Exterior Walls	Excellent
Porch/Stairs/Deck	Fair – worn
Foundation	Good
Storefront & Signage	
Parking Lots	
Other:	
Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good	



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: 17 First Ave  
Zoning or Land Use: B-2  
Commercial/Residential: Residential  
Stories: 1.5  
General Construction: 1942  
Storefront Construction:  
Building Age: 80  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 283,300  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
*x The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Roofing	Good
Windows and Doors	Good
Exterior Walls	Fair – chipped paint on siding and trim
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	

Parking Lots

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: 21 First Ave  
Zoning or Land Use: B-2  
Commercial/Residential: Residential  
Stories: 2  
General Construction: 1900  
Storefront Construction:  
Building Age: 122  
Vacant: yes ☐ no ☒ other:  
Assessed Value: 212,200  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☐ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

<u>Component</u>	<u>Condition</u>
Roofing	Good
Windows and Doors	Fair – older
Exterior Walls	Good
Porch/Stairs/Deck	Good
Foundation	Good
Storefront & Signage	
Parking Lots	

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Property Data

Address: Rockdale Park  
Zoning or Land Use: B-1  
Commercial/Residential:  
Gov't/Institutional  
Stories:  
General Construction:  
Storefront Construction:  
Building Age:  
Vacant: yes ☐ no ☒ other:  
Assessed Value:  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### Component                      Condition

Roofing                      n/a

Windows and Doors                      n/a

Exterior Walls                      n/a

Porch/Stairs/Deck                      n/a

Foundation                      n/a

Storefront & Signage                      n/a

Parking Lots                      n/a

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### **Property Data**

Address: Oliver Ashton Memorial Field  
Zoning or Land Use: R-5  
Commercial/Residential:  
Gov't/Institutional  
Stories:  
General Construction:  
Storefront Construction:  
Building Age:  
Vacant: yes ☐ no ☒ other:  
Assessed Value:  
Other Relevant Data:

### **If the property contributes to slum & blight, please check all that apply.**

- ☐ Physical Deterioration of Building  
☐ Abandoned Property  
☐ Chronic High Occupancy Turnover  
☐ Chronic High Vacancy Rate  
☐ Significant Decline in Property Value  
☐ Abnormally Low Property Value  
☐ Known or Suspected Environmental Contamination  
☐ Other (please explain)  
☒ *The property is not contributing to slum and blight*



Describe the condition of each applicable component using the category definitions found on pages 11-14. Also explain if the turnover/vacancy, property value, and/or contamination boxes which are checked above.

### **Component**                      **Condition**

Roofing                      n/a

Windows and Doors                      n/a

Exterior Walls                      n/a

Porch/Stairs/Deck                      n/a

Foundation                      n/a

Storefront & Signage                      n/a

Parking Lots                      n/a

Other:

Overall Property Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## **Appendix D: CDBG Public Infrastructure Inventory and Ratings**

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Wallen Way

(please use a separate form for each street)

Zoning or Land Use: R-3

#### Infrastructure age

Water line: 1989

Sewer line: 1985

Road surface: 2003

Lighting: 2018

Sidewalk & curbs: 1991

Other Relevant Data:



### Please check the appropriate box.

☐ Physical Deterioration of Public Improvement  
or

☒ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Road Surface	Good
Water Lines	Fair
Sewer Lines	Good
Existing Sidewalk	Good – one side of street
Curbing	Good
Drainage	Good
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Lovelace Lane

(please use a separate form for each street)

Zoning or Land Use: R-3

#### Infrastructure age

Water line: 1950 & 1989

Sewer line: 1985

Road surface: 1999

Lighting: 2018

Sidewalk & curbs: 1991

Other Relevant Data:



### Please check the appropriate box.

☐ Physical Deterioration of Public Improvement  
or

☒ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

#### Component

#### Condition

Road Surface

Good

Water Lines

Fair – 10" cement lined cast iron, 8" ductile iron

Sewer Lines

Good – 8" pvc

Existing Sidewalk

Good – one side of street

Curbing

Good

Drainage

Good

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: South Main Street

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1950

Sewer line: 1985

Road surface: 1995

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☐ Physical Deterioration of Public Improvement  
or

☒ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Good

Water Lines

Fair – 10" cement lined cast iron

Sewer Lines

Good – 8" pvc

Existing Sidewalk

n/a

Curbing

Poor - nonexistent

Drainage

Fair

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Good

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Good

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: South Tessier St

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1999

Sewer line: n/a

Road surface: 1999

Lighting: n/a

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair – some potholes, minor crumbling
Water Lines	Good – 6" ductile iron
Sewer Lines	n/a
Existing Sidewalk	n/a
Curbing	Poor - nonexistent
Drainage	Fair – minor flooding
Parking Lot:	
Lighting:	Poor – no streetlights
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Tessier Lane

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1950 & 1989

Sewer line: n/a

Road surface: 1999

Lighting: n/a

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Poor – gravel

Water Lines

Good – 1" plastic, 8" ductile iron

Sewer Lines

n/a

Existing Sidewalk

n/a

Curbing

Poor - nonexistent

Drainage

Poor

Parking Lot:

Lighting:

Poor – no streetlights

Trees/Landscaping:

Good

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Spring Hill Avenue

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1951

Sewer line: n/a

Road surface: 2002

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Fair – uneven

Water Lines

Fair – 8” and 10” cement lined cast iron

Sewer Lines

n/a

Existing Sidewalk

n/a

Curbing

Poor - nonexistent

Drainage

Fair

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Hudson Street

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1952

Sewer line: 2007

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Poor

Water Lines

Poor – 8" cement lined cast iron

Sewer Lines

Good – 8" pvc

Existing Sidewalk

n/a

Curbing

Poor - nonexistent

Drainage

Poor – minor flooding, debris build up with crumbling edges

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: North Tessier Street

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1952

Sewer line: n/a

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface Poor – alligator cracks, uneven

Water Lines Poor – 6" cement lined cast iron

Sewer Lines n/a

Existing Sidewalk n/a

Curbing Poor - nonexistent

Drainage Poor - flooding

Parking Lot:

Lighting: Good

Trees/Landscaping: Good

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Elston Avenue

(please use a separate form for each street)

Zoning or Land Use: R-3

#### Infrastructure age

Water line: unknown

Sewer line: n/a

Road surface: 1993

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Road Surface	Fair
Water Lines	Unknown
Sewer Lines	n/a
Existing Sidewalk	n/a
Curbing	Poor - nonexistent
Drainage	Poor – debris build up, minor flooding
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Providence Road

(please use a separate form for each street)

Zoning or Land Use: R-3, B-2 & B-1

### Infrastructure age

Water line: 1899, 1918, 1950 & 1953

Sewer line: 1922

Road surface: 2004

Lighting: 2018

Sidewalk & curbs: 2004

Other Relevant Data:



### Please check the appropriate box.

☐ Physical Deterioration of Public Improvement  
or

☒ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Good

Water Lines

Fair – 10" cast iron and 10" cement lined cast iron

Sewer Lines

Poor – 10" clay

Existing Sidewalk

Fair

Curbing

Good – granite

Drainage

Good

Parking Lot:

Fair

Lighting:

Good

Trees/Landscaping:

Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Good



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Cottage Lane

(please use a separate form for each street)

Zoning or Land Use: B-2

### Infrastructure age

Water line: unknown

Sewer line: 1922

Road surface: unknown

Lighting: n/a

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement

or

☐ The public improvement is not contributing to slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface      Poor – gravel, potholes

Water Lines      Unknown

Sewer Lines      Poor – 12" clay

Existing Sidewalk      n/a

Curbing      Poor – nonexistent

Drainage      Poor – flooding

Parking Lot:

Lighting:      Poor – no streetlights

Trees/Landscaping:      Poor

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Central Avenue

(please use a separate form for each street)

Zoning or Land Use: B-2

### Infrastructure age

Water line: unknown

Sewer line: 1940

Road surface: 1998

Lighting: n/a

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Poor – gravel

Water Lines

Unknown

Sewer Lines

Fair – 6" clay

Existing Sidewalk

n/a

Curbing

Poor – nonexistent

Drainage

Poor – flooding

Parking Lot:

Lighting:

Poor – no streetlights

Trees/Landscaping:

Poor

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: First Avenue

(please use a separate form for each street)

Zoning or Land Use: B-2

#### Infrastructure age

Water line: 1950

Sewer line: 1940

Road surface: 1999

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

#### Component

#### Condition

Road Surface	Fair – some cracks
Water Lines	Poor – 10” cement lined cast iron
Sewer Lines	Fair – 6” clay
Existing Sidewalk	n/a
Curbing	Poor – nonexistent
Drainage	Fair – minor flooding
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Beanes Lane

(please use a separate form for each street)

Zoning or Land Use: B-1 and R-5

### Infrastructure age

Water line: 1904

Sewer line: 1922

Road surface: 1977

Lighting: 2018

Sidewalk & curbs: unknown

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Road Surface	Fair – alligator cracking, uneven
Water Lines	Fair – 10" cast iron
Sewer Lines	Poor – 6" and 8" clay
Existing Sidewalk	Poor – uneven, cracking
Curbing	Fair – some granite, minimal curbing
Drainage	Poor – flooding
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Poor
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Church Avenue

(please use a separate form for each street)

Zoning or Land Use: R-2, R-3 & R-5

### Infrastructure age

Water line: 1944, 1956 & 1978

Sewer line: 1953

Road surface: 1966

Lighting: 2018

Sidewalk & curbs: 1953

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface	Poor – alligator cracking, potholes, uneven
Water Lines	Fair – 10” cast iron, 8” cement lined cast iron, 10” ductile iron
Sewer Lines	Fair – 8” clay
Existing Sidewalk	Poor – inconsistent, significant cracking
Curbing	Poor – crumbling, inconsistent
Drainage	Poor
Parking Lot:	Fair
Lighting:	Good
Trees/Landscaping:	Good
Park/Playground:	Fair – Rockdale Playground
Other:	

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Cross Place

(please use a separate form for each street)

Zoning or Land Use: R-5

#### Infrastructure age

Water line: 1904

Sewer line: 1922

Road surface: 1988

Lighting: 2018

Sidewalk & curbs: 1933

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Road Surface	Poor – uneven with cracks
Water Lines	Poor – 4” cast iron
Sewer Lines	Poor – 8” clay
Existing Sidewalk	Poor – uneven with cracks
Curbing	Poor – nonexistent in some areas
Drainage	Poor – flooding
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating: (Excellent / Good / Fair / Poor) briefly state why.	Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Taft Street

(please use a separate form for each street)

Zoning or Land Use: R-5

### Infrastructure age

Water line: 1964

Sewer line: 1922

Road surface: 1988

Lighting: 2018

Sidewalk & curbs: 1936

Other Relevant Data:

### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface      Poor – major cracking on southern end of street

Water Lines      Fair – 8" cement lined cast iron

Sewer Lines      Poor – 8" clay

Existing Sidewalk      Fair – uneven with cracks

Curbing      Poor – nonexistent in most areas

Drainage      Poor – flooding

Parking Lot:

Lighting:      Good

Trees/Landscaping:      Poor

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: McBride Street

(please use a separate form for each street)

Zoning or Land Use: R-5

### Infrastructure age

Water line: unknown

Sewer line: 1922

Road surface: 2000

Lighting: 2018

Sidewalk & curbs: 1953

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface Fair – uneven with divots and minor cracks

Water Lines Unknown

Sewer Lines Poor – 8" clay

Existing Sidewalk Good

Curbing Good

Drainage Fair – some flooding

Parking Lot:

Lighting: Good

Trees/Landscaping: Good

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Plantation Street

(please use a separate form for each street)

Zoning or Land Use: R-3 and R-5

#### Infrastructure age

Water line: 1904

Sewer line: 1922

Road surface: 2005

Lighting: 2008

Sidewalk & curbs: unknown

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

<u>Component</u>	<u>Condition</u>
Road Surface	Fair
Water Lines	Fair – 8" cast iron and 6" cement lined cast iron
Sewer Lines	Poor – 8" clay
Existing Sidewalk	Fair – uneven in some areas, only on one side of the street
Curbing	Fair
Drainage	Poor – flooding
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	
Other:	
Overall Rating:	(Excellent / Good / Fair / Poor) briefly state why. Fair



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Arrowhead Avenue

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1904 & 1950

Sewer line: 1953

Road surface: 1983

Lighting: n/a

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface Fair – a lot of cracks, extension of street is gravel and in poor condition

Water Lines Fair – 8" cast iron and 6" cement lined cast iron

Sewer Lines Fair – 8" clay

Existing Sidewalk n/a

Curbing Poor – no curbing

Drainage Poor – flooding

Parking Lot:

Lighting: Poor – no lighting

Trees/Landscaping: Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Legion Way

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1956

Sewer line: unknown

Road surface: unknown

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface: Poor – alligator cracks, a lot of patchwork and divots

Water Lines: Poor – 1" copper

Sewer Lines: Good – 8" pvc

Existing Sidewalk: n/a

Curbing: Poor – no curbing

Drainage: Poor – flooding

Parking Lot:

Lighting: Good

Trees/Landscaping: Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Duggan Way

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1956

Sewer line: n/a

Road surface: 2004

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface Poor – a lot of cracks

Water Lines Poor – 1" copper

Sewer Lines n/a

Existing Sidewalk n/a

Curbing Poor – no curbing

Drainage Poor – flooding

Parking Lot:

Lighting: Good

Trees/Landscaping: Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor



## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: School Street

(please use a separate form for each street)

Zoning or Land Use: B-1, R-2, R-3 & R-5

### Infrastructure age

Water line: 1965, 1979, 1980 & 1985

Sewer line: n/a

Road surface: unknown

Lighting: 2018

Sidewalk & curbs: unknown

Other Relevant Data:

### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight



Describe the condition of each applicable component using the category definitions found on pages 11-14.

<b><u>Component</u></b>	<b><u>Condition</u></b>
Road Surface	Fair – minor cracks, School St extension is poor with major cracks and potholes
Water Lines	Fair – 12” and 16” ductile iron, 12” cement lined cast iron
Sewer Lines	n/a
Existing Sidewalk	Fair – minor cracks
Curbing	Fair
Drainage	Fair – minor flooding
Parking Lot:	
Lighting:	Good
Trees/Landscaping:	Fair
Park/Playground:	Good – Rockdale Park
Other:	

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Emond Avenue

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1979

Sewer line: unknown

Road surface: 1946

Lighting: n/a

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface      Poor – alligator cracks, erosion, flooding, narrow, potholes

Water Lines      Fair – 6" ductile iron

Sewer Lines      Poor – 6" clay

Existing Sidewalk      N/a

Curbing      Poor – no curbing

Drainage      Poor – flooding

Parking Lot:

Lighting:      Poor – no lighting

Trees/Landscaping:      Fair

Park/Playground:

Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Poor

## 1. NAME OF SLUM & BLIGHT AREA: ROCKDALE

### Public Improvement Data

Street Name: Upton Street

(please use a separate form for each street)

Zoning or Land Use: R-3

### Infrastructure age

Water line: 1965 & 1979


Sewer line: 2001

Road surface: 1946

Lighting: 2018

Sidewalk & curbs: n/a

Other Relevant Data:



### Please check the appropriate box.

☒ Physical Deterioration of Public Improvement  
or

☐ The public improvement is not contributing to  
slum and blight

Describe the condition of each applicable component using the category definitions found on pages 11-14.

### Component

### Condition

Road Surface

Fair – minor cracks

Water Lines

Good – 12" cement lined cast iron and 16" ductile iron

Sewer Lines

Good – 8" pvc

Existing Sidewalk

n/a

Curbing

Poor – no curbing

Drainage

Poor – debris build up, cracking along edges

Parking Lot:

Lighting:

Good

Trees/Landscaping:

Good

Park/Playground:


Other:

Overall Rating: (Excellent / Good / Fair / Poor) briefly state why. Fair



## Appendix E: Maps

# Rockdale Infrastructure Rating Map



6/13/2022, 4:18:47 PM


Rockdale Infrastructure Overall Rating

Good

Fair


Poor

Northbridge SBIA Rockdale



Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri

# Rockdale Property Rating Map



7/1/2022, 1:01:11 PM

Northbridge\_Parcel\_Rating

Excellent

Good

Fair

Poor

unknown

Other

Northbridge SBIA Rockdale

1:18,056

0 0.1 0.2 0.4 mi

0 0.17 0.35 0.7 km

Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri

PVPC

Map data © OpenStreetMap contributors, Microsoft, Facebook, Inc. and its affiliates, Esri Community Maps contributors, Map layer by Esri | Massachusetts Department of Transportation (MassDOT), MassGIS |